

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Noor Amran, Noor Yussyuhaila

Date: 03 May 2023

Preliminary Advice

Vehicle No	: SKL1173J	Accident Date	: 02/02/2023
Make	: AUDI A6 DESIGN	Policy No.	: 7220130725
Assignment Date	: 08/02/2023	Excess	: S\$800.00
Date of Inspection	: 06/02/2023	Est. Duration of Repair	: 8
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	79,362.90 (Est \$77,461.00 + Supp \$1,901.00)
Revised Amount	:S\$	41,139.36 (inclu. Supp \$1,407.52)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	41,139.36
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	247,000.00
COE / PARF Rebate	:S\$	150,869.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,131.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on Supplementary Items & Final Cost of Repair.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.