



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0137/2023/EQ
DATE : 6-Feb-23
WIP : 61629

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/2/2023

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAU KIAN KOON
ADDRESS : 28 FLORA DRIVE
#07-58
SINGAPORE 506951
TELEPHONE : HP +65 98211159
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220130725
VEHICLE NO : SKL 1173 J
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 16/11/2022
ENGINE NO : DKY 016361
CHASSIS NO : WAUZZZF20NN006334
MILEAGE : 7,816
DATE IN : 3-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Feb-23
PLACE OF ACCIDENT : TPE TOWARDS CHANGI, BEFORE PUNGGOL EAST FLYOVER,
IN FRONT OD GLOBAL INDIA INTERNATIONAL SCHOOL.
COORDINATES: 1.39591, 103.90511

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 1173]

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 / 500	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 ? / phh	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ? /	
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILTIAE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 X 17	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. (TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION) RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 1000 + 1500 /	
TOTAL LABOUR CHARGES		\$ 11,040.00	

* Additional 3 working days. /

Paul
 16/02/23

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 11731

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, X BONNET, HINGES, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS. X	S 7,500.00	1260
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S 192.00	
TOTAL LABOUR CHARGES		: \$ 18,732.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>de</i>	1	\$ 3,187.00		2549.60
2	FRONT BUMPER FIXING PARTS <i>? Xan</i>	1	\$ 689.00	X	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>? can</i>	1	\$ 263.00	/	210.00
4	FRONT BUMPER ADAPTER - LH / RH <i>? can</i>	2	\$ 94.00		74.40
5	FRONT BUMPER REINFORCEMENT - LH / RH <i>? Xan</i>	2	\$ 264.00	X	
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>Xan</i>	1	\$ 181.00	X	
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>Xan</i>	1	\$ 248.00	X	
8	FRONT BUMPER SPOILER <i>? Xan</i>	1	\$ 298.00	X	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Xan</i>	2	\$ 1,026.00	X	
10	FRONT BUMPER AIR GUIDE - LH / RH <i>Xan</i>	2	\$ 78.00	X	
11	FRONT BUMPER AIR GUIDE - LH / RH <i>Xan</i>	2	\$ 62.00	X	
12	RADIATOR GRILLE <i>can</i>	1	\$ 2,603.00		2082.40
13	RADIATOR GRILLE COVER <i>? Xan</i>	1	\$ 65.00	X	
14	RADIATOR GRILLE COVER CAP <i>can</i>	1	\$ 59.00		46.48
15	RADIATOR GRILLE BRACKET <i>? Xan</i>	1	\$ 111.00	X	
16	FRONT PARKING AID SENSOR - INNER / OUTER <i>? Xan</i>	4	\$ 1,196.00	X	
17	FRONT PARKING AID SEAL RING <i>Xan</i>	4	\$ 11.00	X	
18	FRONT BUMPER WIRING SET <i>? Xan</i>	1	\$ 648.00	X	
19	FRONT BUMPER FOAM FILLER PIECE <i>can</i>	1	\$ 267.00		213.20
20	FRONT BUMPER REINFORCEMENT BEAM <i>? Xan</i>	1	\$ 1,140.00	X	
SUB TOTAL SPARE PARTS		:	\$ 12,490.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER SUPPORT - LH / RH <i>can ✓</i>	2	S 71.00		56.80
22	FRONT BUMPER GUIDE SECTION - LH / RH <i>? Xnn</i>	2	S 106.00	X	
23	FRONT BUMPER BRACKET - LH / RH <i>? Xnn</i>	2	S 130.00	X	
24	FRONT BUMPER TOP COVER <i>der</i>	1	S 149.00		118.80
25	AIR CONDITIONER STICKER <i>ner ✓</i>	1	S 36.00		28.64
26	CAUTION SIGN STICKER <i>ner ✓</i>	1	S 17.00		13.28
27	HORN LOW TONE - LH <i>? Xnn</i>	1	S 244.00	X	
28	HORN HIGH TONE - RH <i>? Xnn</i>	1	S 157.00	X	
29	HORN BRACKET - LH / RH <i>? Xnn</i>	2	S 112.00	X	
30	FRONT FENDER - LH / RH <i>? Xnn</i>	2	S 3,492.00	X	
31	FRONT FENDER BRACE - LH / RH <i>? Xnn</i>	2	S 292.00	X	
32	FRONT FENDER BRACKET - LH / RH UPPER <i>? Xnn</i>	2	S 104.00	X	
33	FRONT WHEEL HOUSING LINER - LH / RH <i>Xnn</i>	2	S 644.00	X	
34	FRONT WHEEL SPOILER - LH / RH <i>Xnn</i>	2	S 392.00	X	
35	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH <i>? Xnn</i>	2	S 120.00	X	
36	FRONT WHEEL SPOILER TRIM BRACKET - LH / RH <i>? Xnn</i>	2	S 96.00	X	
37	BONNET HOOD SEAL COVER - LH / RH <i>? Xnn</i>	2	S 84.00	X	
38	BONNET LOCK COVER - LH / RH <i>can ✓</i>	2	S 104.00		82.40
39	BONNET <i>bt ✓</i>	1	S 5,971.00		4776.80
40	BONNET HINGE - LH / RH <i>bt ✓</i>	2	S 406.00		324.80
SUB TOTAL SPARE PARTS			: \$ 12,727.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	BONNET ATTACHMENT PARTS ? <i>Xan</i>	1	S 259.00	X	
42	BONNET IMPACT PROTECTION - LH / RH / CENTER <i>new</i>	3	S 99.00		78.48
43	BONNET STRIKER - LH / RH <i>9.6t</i>	2	S 260.00		208.00
44	BONNET LOCK - LH / RH ? <i>Xan</i>	2	S 488.00	X	
45	BONNET RELEASE ELEMENT <i>7.6t</i>	1	S 69.00		54.80
46	BONNET RELEASE LEVER <i>7.6t</i>	1	S 16.00		12.16
47	BONNET BOWDEN CABLE - CENTER ? <i>Xan</i>	1	S 67.00	X	
48	BONNET RELEASE CABLE COVER ? <i>Xan</i>	1	S 12.00	X	
49	HEADLIGHT MOUNTING - (LH / RH) ? <i>cm</i>	2	S 280.00		223.20
50	HEADLIGHT - LH / RH <i>cm</i>	2	S 19,424.00		15,539.20
51	HEADLIGHT HOSE - LH / RH ? <i>Xan</i>	2	S 68.00	X	
52	LIFT CYLINDER - LH / RH ? <i>Xan</i>	2	S 460.00	X	
53	LIFT CYLINDER BRACKET - LH / RH ? <i>Xan</i>	2	S 16.00	X	
54	LIFT CYLINDER HOSE ? <i>Xan</i>	1	S 208.00	X	
55	LOCK CARRIER ? <i>cm</i>	1	S 1,448.00		1158.40
56	LOCK CARRIER SUPPORT - LH / RH ? <i>Xan</i>	2	S 52.00	X	
57	CHARGE AIR COOLER <i>H</i>	1	S 692.00		553.60
58	CHARGE AIR COOLER PRESSURE HOSE - RH ? <i>Xan</i>	1	S 354.00	X	
59	CHARGE AIR COOLER PRESSURE PIPE - LH ? <i>Xan</i>	1	S 434.00	X	
60	A/C CONDENSER WITH DRYER ? <i>6t</i>	1	S 724.00		578.80
SUB TOTAL SPARE PARTS		:	\$ 25,430.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	A/C CONDENSER REFRIGERANT LINE ? X17	1	\$ 293.00	X	
62	A/C CONDENSER REFRIGERANT LINE ? X17	1	\$ 312.00	X	
63	A/C CONDENSER REFRIGERANT LINE ? X17	1	\$ 293.00	X	
64	OUTSIDE TEMPERATURE SENSOR BRACKET ? X17	1	\$ 27.00	X	
65	RADIATOR ? 54	1	\$ 1,103.00		882.40
66	READY-MIX COOLANT ? n	6	\$ 326.00		260.16
67	RADIATOR FAN RING ? X17	1	\$ 318.00	X	
68	RADIATOR FAN WITH CONTROL UNIT ? Sca	1	\$ 2,131.00		1704.80
69	RADIATOR AIR GUIDE - (LH / RH) ? X17	2	\$ 100.00		79.68
70	RADIATOR AIR GUIDE - UPPER / LOWER ? X17	2	\$ 78.00	X	
71	RADIATOR INTAKE AIR DUCT ? X17	1	\$ 54.00	X	
72	RADIATOR INTAKE AIR DUCT ? X17	1	\$ 98.00	X	
73	RADIATOR AIR FILTER ? X17	1	\$ 348.00	X	
74	RADIATOR INTAKE HOSE ? X17	1	\$ 180.00	X	
75	AIR MASS METER ? X17	1	\$ 639.00	X	
76	FRONT WATER DEFLECTOR STRIP - LH / RH X17	2	\$ 140.00	X	
77	FRONT WINDOW GUIDE CHROME TRIM STRIP - LH / RH X17	2	\$ 608.00	X	
78	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH X17	2	\$ 474.00	X	
79	OUTER	S/N	\$ 60.00	✓	
79	FRONT NUMBER PLATE 64		\$ 500.00	✓	28.56
80	SUNDRIES ? n				
TOTAL SPARE PARTS			\$ 58,729.00		
TOTAL LABOUR CHARGES			\$ 18,732.00		
GRAND TOTAL			\$ 77,461.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasuk - Hp 90010068
: 06/02/23 P1540
: 5 days
: EXCESS.THA
: Repair
: Resin before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0137/2023/EQ
Date 15-Feb-23
Service Advisor CHANG
Pages 1 of 1
Regn No SKL 1173 J
Model No AUDI A6 DESIGN 2.0 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	Camera <i>scr / cr /</i>	\$ 1,115.00	892
2	Coolant pipe <i>cr /</i>	\$ 44.40	35.52
3	Upper closing element <i>cr /</i>	\$ 262.50	xnn
Labour			
1	To carry out calibration for front bumper camera, distance regulation and radar sensor	\$ 480.00	
GRAND TOTAL		\$ 1,421.90	\$ -

xtra 3 days

Rafael
16/02/23

For Premium Automobiles Pte Ltd

Authorised Signature