



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0137/2023/EQ  
**DATE** : 6-Feb-23  
**WIP** : 61629

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/2/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR LAU KIAN KOON  
**ADDRESS** : 28 FLORA DRIVE  
#07-58  
SINGAPORE 506951  
**TELEPHONE** : HP +65 98211159  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220130725  
**VEHICLE NO** : **SKL 1173 J**  
**MODEL CODE** : AUDI A6 DESIGN 2.0 TFSI S  
**MODEL YEAR** : 16/11/2022  
**ENGINE NO** : DKY 016361  
**CHASSIS NO** : WAUZZZF20NN006334  
**MILEAGE** : 7,816  
**DATE IN** : 3-Feb-23  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 2-Feb-23  
**PLACE OF ACCIDENT** : TPE TOWARDS CHANGI, BEFORE PUNGGOL EAST FLYOVER,  
IN FRONT OD GLOBAL INDIA INTERNATIONAL SCHOOL.  
COORDINATES: 1.39591, 103.90511

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 1173 J

| S/N                         | NATURE OF JOBS                                                                                                                                                                                              | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                                            | S/N \$ 480.00 /       |                            |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                      | S/N \$ 800.00 / 500   |                            |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.                                                                  | S/N \$ 1,600.00 ?     |                            |
| 4                           | TO CARRY OUT VACUUM AND REGAS FOR R1234.                                                                                                                                                                    | S/N \$ 1,200.00 ?     |                            |
| 5                           | TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.                                                                 | S/N \$ 560.00 X       |                            |
| 6                           | TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 6,400.00 / 1000    |                            |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                             | <b>: \$ 11,040.00</b> |                            |



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 1173 J**

| S/N                  | NATURE OF JOBS                                                                                          | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|----------------------|---------------------------------------------------------------------------------------------------------|-------------------|----------------------------|
| 7                    | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS. | \$ 7,500.00       | 1260                       |
| 8                    | TO CARRY OUT DIAGNOSTIC CHECK.                                                                          | S/N \$ 192.00     |                            |
| TOTAL LABOUR CHARGES |                                                                                                         | : \$ 18,732.00    |                            |



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731

|                              |                                                      |     | DAMAGED PARTS & PRICES |                  |
|------------------------------|------------------------------------------------------|-----|------------------------|------------------|
| S/N                          | PARTS DESCRIPTION                                    | QTY | S/NETT                 | REMARKS          |
| 1                            | FRONT BUMPER <i>de/</i>                              | 1   | \$                     | 3,187.00         |
| 2                            | FRONT BUMPER FIXING PARTS ?                          | 1   | \$                     | 689.00           |
| 3                            | FRONT BUMPER CLOSING ELEMENT - CENTER ?              | 1   | \$                     | 263.00           |
| 4                            | FRONT BUMPER ADAPTER - LH / RH ?                     | 2   | \$                     | 94.00            |
| 5                            | FRONT BUMPER REINFORCEMENT - LH / RH ?               | 2   | \$                     | 264.00           |
| 6                            | FRONT BUMPER GRILLE - LOWER CENTRE <del>XX</del>     | 1   | \$                     | 181.00           |
| 7                            | FRONT BUMPER CLOSING ELEMENT - LOWER <del>X</del>    | 1   | \$                     | 248.00           |
| 8                            | FRONT BUMPER SPOILER ? <del>X</del> ?                | 1   | \$                     | 298.00           |
| 9                            | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <del>X</del> | 2   | \$                     | 1,026.00         |
| 10                           | FRONT BUMPER AIR GUIDE - LH / RH <del>X</del>        | 2   | \$                     | 78.00            |
| 11                           | FRONT BUMPER AIR GUIDE - LH / RH <del>X</del>        | 2   | \$                     | 62.00            |
| 12                           | RADIATOR GRILLE <i>cm-</i>                           | 1   | \$                     | 2,603.00         |
| 13                           | RADIATOR GRILLE COVER ?                              | 1   | \$                     | 65.00            |
| 14                           | RADIATOR GRILLE COVER CAP <i>cm-</i>                 | 1   | \$                     | 59.00            |
| 15                           | RADIATOR GRILLE BRACKET ?                            | 1   | \$                     | 111.00           |
| 16                           | FRONT PARKING AID SENSOR - INNER / OUTER ?           | 4   | \$                     | 1,196.00         |
| 17                           | FRONT PARKING AID SEAL RING <i>de/</i>               | 4   | \$                     | 11.00            |
| 18                           | FRONT BUMPER WIRING SET ?                            | 1   | \$                     | 648.00           |
| 19                           | FRONT BUMPER FOAM FILLER PIECE <i>cm-</i>            | 1   | \$                     | 267.00           |
| 20                           | FRONT BUMPER REINFORCEMENT BEAM ?                    | 1   | \$                     | 1,140.00         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                      | :   | <b>\$</b>              | <b>12,490.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 11731**

|                              |                                                         |          | DAMAGED PARTS & PRICES |                  |  |
|------------------------------|---------------------------------------------------------|----------|------------------------|------------------|--|
| S/N                          | PARTS DESCRIPTION                                       | QTY      | S/NETT                 | REMARKS          |  |
| 21                           | FRONT BUMPER SUPPORT - LH / RH <i>cm / ?</i>            | 2        | \$                     | 71.00            |  |
| 22                           | FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>           | 2        | \$                     | 106.00           |  |
| 23                           | FRONT BUMPER BRACKET - LH / RH <i>?</i>                 | 2        | \$                     | 130.00           |  |
| 24                           | FRONT BUMPER TOP COVER <i>dr /</i>                      | 1        | \$                     | 149.00           |  |
| 25                           | AIR CONDITIONER STICKER <i>new /</i>                    | 1        | \$                     | 36.00            |  |
| 26                           | CAUTION SIGN STICKER <i>new /</i>                       | 1        | \$                     | 17.00            |  |
| 27                           | HORN LOW TONE - LH <i>?</i>                             | 1        | \$                     | 244.00           |  |
| 28                           | HORN HIGH TONE - RH <i>?</i>                            | 1        | \$                     | 157.00           |  |
| 29                           | HORN BRACKET - LH / RH <i>?</i>                         | 2        | \$                     | 112.00           |  |
| 30                           | FRONT FENDER - LH / RH <i>?</i>                         | 2        | \$                     | 3,492.00         |  |
| 31                           | FRONT FENDER BRACE - LH / RH <i>?</i>                   | 2        | \$                     | 292.00           |  |
| 32                           | FRONT FENDER BRACKET - LH / RH UPPER <i>?</i>           | 2        | \$                     | 104.00           |  |
| 33                           | FRONT WHEEL HOUSING LINER - LH / RH <i>X</i>            | 2        | \$                     | 644.00           |  |
| 34                           | FRONT WHEEL SPOILER - LH / RH <i>X</i>                  | 2        | \$                     | 392.00           |  |
| 35                           | FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH <i>?</i> | 2        | \$                     | 120.00           |  |
| 36                           | FRONT WHEEL SPOILER TRIM BRACKET - LH / RH <i>?</i>     | 2        | \$                     | 96.00            |  |
| 37                           | BONNET HOOD SEAL COVER - LH / RH <i>?</i>               | 2        | \$                     | 84.00            |  |
| 38                           | BONNET LOCK COVER - LH / RH <i>cm /</i>                 | 2        | \$                     | 104.00           |  |
| 39                           | BONNET <i>bt /</i>                                      | 1        | \$                     | 5,971.00         |  |
| 40                           | BONNET HINGE - LH / RH <i>bt /</i>                      | 2        | \$                     | 406.00           |  |
| <b>SUB TOTAL SPARE PARTS</b> |                                                         | <b>:</b> | <b>\$</b>              | <b>12,727.00</b> |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 1173 J

|                              |                                                       |          | DAMAGED PARTS & PRICES |         |
|------------------------------|-------------------------------------------------------|----------|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                     | QTY      | S/NETT                 | REMARKS |
| 41                           | BONNET ATTACHMENT PARTS ?                             | 1        | \$ 259.00              |         |
| 42                           | BONNET IMPACT PROTECTION - LH / RH / CENTER <i>na</i> | 3        | \$ 99.00               |         |
| 43                           | BONNET STRIKER - LH / RH ?                            | 2        | \$ 260.00              |         |
| 44                           | BONNET LOCK - LH / RH ?                               | 2        | \$ 488.00              |         |
| 45                           | BONNET RELEASE ELEMENT ?                              | 1        | \$ 69.00               |         |
| 46                           | BONNET RELEASE LEVER <i>X</i>                         | 1        | \$ 16.00               |         |
| 47                           | BONNET BOWDEN CABLE - CENTER ?                        | 1        | \$ 67.00               |         |
| 48                           | BONNET RELEASE CABLE COVER ?                          | 1        | \$ 12.00               |         |
| 49                           | HEADLIGHT MOUNTING - LH / RH ?                        | 2        | \$ 280.00              |         |
| 50                           | HEADLIGHT - LH / RH <i>cm</i>                         | 2        | \$ 19,424.00           |         |
| 51                           | HEADLIGHT HOSE - LH / RH ?                            | 2        | \$ 68.00               |         |
| 52                           | LIFT CYLINDER - LH / RH ?                             | 2        | \$ 460.00              |         |
| 53                           | LIFT CYLINDER BRACKET - LH / RH ?                     | 2        | \$ 16.00               |         |
| 54                           | LIFT CYLINDER HOSE ?                                  | 1        | \$ 208.00              |         |
| 55                           | LOCK CARRIER ?                                        | 1        | \$ 1,448.00            |         |
| 56                           | LOCK CARRIER SUPPORT - LH / RH ?                      | 2        | \$ 52.00               |         |
| 57                           | CHARGE AIR COOLER <i>H</i>                            | 1        | \$ 692.00              |         |
| 58                           | CHARGE AIR COOLER PRESSURE HOSE - RH ?                | 1        | \$ 354.00              |         |
| 59                           | CHARGE AIR COOLER PRESSURE PIPE - LH ?                | 1        | \$ 434.00              |         |
| 60                           | A/C CONDENSER WITH DRYER ?                            | 1        | \$ 724.00              |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                       | <b>:</b> | <b>\$ 25,430.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 1173 J

|                             |                                                               |     | DAMAGED PARTS & PRICES |                     |
|-----------------------------|---------------------------------------------------------------|-----|------------------------|---------------------|
| S/N                         | PARTS DESCRIPTION                                             | QTY | S/NETT                 | REMARKS             |
| 61                          | A/C CONDENSER REFRIGERANT LINE ?                              | 1   | \$                     | 293.00              |
| 62                          | A/C CONDENSER REFRIGERANT LINE ?                              | 1   | \$                     | 312.00              |
| 63                          | A/C CONDENSER REFRIGERANT LINE ?                              | 1   | \$                     | 293.00              |
| 64                          | OUTSIDE TEMPERATURE SENSOR BRACKET ?                          | 1   | \$                     | 27.00               |
| 65                          | RADIATOR ?                                                    | 1   | \$                     | 1,103.00            |
| 66                          | READY-MIX COOLANT ?                                           | 6   | \$                     | 326.00              |
| 67                          | RADIATOR FAN RING ?                                           | 1   | \$                     | 318.00              |
| 68                          | RADIATOR FAN WITH CONTROL UNIT ?                              | 1   | \$                     | 2,131.00            |
| 69                          | RADIATOR AIR GUIDE - LH / RH ?                                | 2   | \$                     | 100.00              |
| 70                          | RADIATOR AIR GUIDE - UPPER / LOWER ?                          | 2   | \$                     | 78.00               |
| 71                          | RADIATOR INTAKE AIR DUCT ?                                    | 1   | \$                     | 54.00               |
| 72                          | RADIATOR INTAKE AIR DUCT ?                                    | 1   | \$                     | 98.00               |
| 73                          | RADIATOR AIR FILTER ?                                         | 1   | \$                     | 348.00              |
| 74                          | RADIATOR INTAKE HOSE ?                                        | 1   | \$                     | 180.00              |
| 75                          | AIR MASS METER ?                                              | 1   | \$                     | 639.00              |
| 76                          | FRONT WATER DEFLECTOR STRIP - LH / RH X                       | 2   | \$                     | 140.00              |
| 77                          | FRONT WINDOW GUIDE CHROME TRIM STRIP - LH / RH X              | 2   | \$                     | 608.00              |
| 78                          | FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH X<br>OUTER | 2   | \$                     | 474.00              |
| 79                          | FRONT NUMBER PLATE 54 /                                       | S/N | \$                     | 60.00               |
| 80                          | SUNDRIES ?                                                    |     | \$                     | 500.00              |
| <b>TOTAL SPARE PARTS</b>    |                                                               |     | :                      | <b>\$ 58,729.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                                               |     | :                      | <b>\$ 18,732.00</b> |
| <b>GRAND TOTAL</b>          |                                                               |     | :                      | <b>\$ 77,461.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

: Rasul - Hp 90010068  
: 06/02/23 P1540  
: 5 days  
: EXCESS.THA  
: Repair  
: Resurvey before paint

**PLEASE NOTE**

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT