



南方摩哆 Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

06-Feb-2023

India International Insurance Pte Ltd

64 Cecil Street #05-00

IOB Building

SINGAPORE (049711)

Dear Sirs,

RE: Cost of repair to Honda CB400 - FBA8635L

1pc of Rear Fork	S\$	2,200.00
1pc of Rear Tail Cover		350.00
1pc of Rear Tail Light		180.00
1pc of Rear Signal Light		45.00
1pc of Rear Mudguard		140.00
1pc of Footrest Bracket LH		240.00
1pc of Engine Guard		180.00
1pc of Gear Lever		110.00
1pc of Handle Bar		160.00
1pc of Mirror Set		85.00
1pc of Brake Lever		65.00
1set of Front Brake Disc		900.00
1pc of Front Fork		1,300.00
1pc of Rear Sport Rim		850.00
1pc of Front Sport Rim		750.00
1pc of Meter Set		980.00
1set of Exhaust Pipe		1,800.00
1pc of Handle Grip		25.00
		<hr/>
		10,360.00
	Less 10%	1,036.00
		<hr/>
	Nett	9,324.00
	Transport	40.00
	IU	165.00
	Spary Fuel Tank	450.00
	Jack Rear Body	300.00
	Labour	350.00
		<hr/>
		<u>\$10,629.00</u>

Yours Faithfully,
Southern Motor



Date: 06 Feb 2023

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
SINGAPORE (049711)

Dear Sirs,

RE: ACCIDENT INVOLING FBA8635L AND SHD2368K ALONG
TPE, Singapore ON 16-01-2023 AT 04:30 PM

Please be informed that the above-said motorcycle bearing registration no: FBA8635L
was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at
Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.