

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 9-Feb-23

Estimate no. 1219

Plate No. FBR9331S
Model. XSR155

		Surveyor's columns		
S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK ALIGNMENT	\$ 300.00	? dent + Local Repair	
2	STEERING CONE	\$ 180.00	? dent + 60	
3	HANDLE BAR	\$ 350.00	? dent + 120	
4	HANDLE BALANCER	\$ 180.00	scr 50	
5	BRAKE LEVER	\$ 100.00	scr 25	
6	MIRROR SET	\$ 220.00	scr 55	
7	BRAKE PEDAL	\$ 250.00	scr 50	
8	EXHAUST COVER (MATTE BLACK)	\$ 200.00	scr 50	
9	EXHAUST COVER (SLIVER)	\$ 180.00	cra 40	
10	BOX	\$ 300.00	scr 180	
11	BATTERY	\$ 120.00	? weak 50	
12	LABOUR	\$ 500.00	150	

Fork Local Repair \$ 80
17/2/23

2 days

L/S

8/2/23

4pm

1st 90097659

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P = 680

w/b = 68

= 612

T = 842

20% = 168.40

= 673.6

≈ 650

\$ 2,880.00
Sub Total : \$ 2,592.00
GST 8% \$ 207.36
Total: \$ 2,799.36

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.