

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001331/APA3Q2**Date:** 10/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210153899
Claimant Vehicle No :	GBJ8649A	Insured Vehicle No :	SBA113D
Date of Loss:	29/11/2022	Nature of Claim:	TP
		Claim No:	6387201789SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ8649A		
Make & Model:	KIA K2500 6M/T, 2.5 D (M)	Engine No:	D4CBK864135
Reg. Date:	23/09/2019 (Man. Year: 2019)	Chassis No:	KNCSJX76LK7384207
Colour:	White	Odometer:	76705 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,006.29	2,416.09	2,590.20	51.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	1,130.00	2,690.00	70.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,826.29	3,546.09	5,280.20	59.82
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	8,826.29	2,800.00	6,026.29	68.28
+ GST 8.00/8.00% (S\$)	706.10	224.00	482.10	68.28
Nett Amount (S\$)	9,532.39	3,024.00	6,508.39	68.28
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,426.00		

INSPECTION

Date of Assignment:	22/12/2022	
Date Inspected:	22/12/2022	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,050.00 FL	*1,050.00 FL
2	3		*REAR TAILGATE HINGE L/R	Not Necessary	282.00 FL	*- FL
3	2		*REAR TAILGATE LOCK CATCH L/R	Not Necessary	316.00 FL	*- FL
4	2		*REAR LAMP L/R WITH REVERSE LAMP	Cracked	450.00 FL	*450.00 FL
5	2		*REAR LAMP PANEL L/R	Dented	716.00 FL	*716.00 FL
6	2		*REVERSE SENSOR L/R	Damaged	270.00 FL	*270.00 FL
7	2		*REVERSE SENSOR BRACKET L/R	Not Necessary	174.00 FL	*- FL
8	1		*REAR NO PLATE LAMP	Not Necessary	73.00 FL	*- FL
9	1		*REAR FLOOR PANEL PLATFORM	Repair	715.00 FL	*- FL
10	1		*REAR TAILGATE 13 PAX STICKER	Necessary	28.00 FL	*28.00 FL
11	1		*REAR TAILGATE 70KM/H STICKER	Necessary	28.00 FL	*28.00 FL
12	1		*REAR TAILGATE KIA MOTOR STICKER	Necessary	98.10 FL	*98.10 FL
13	1		*REAR BUMPER	Repair	1,318.00 FL	*- FL
14	1		*REAR NO PLATE	Deformed	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,558.10	2,680.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	551.81	264.01
Total Parts (\$\$)	5,006.29	2,416.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	120.00	30.00
2	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	2,200.00	500.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,500.00	600.00
Gross Labour Cost (S\$)			3,820.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >