

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 13 Feb 2023

**Preliminary Advice**

Vehicle No	: SMT7221Z	Accident Date	: 04/02/2023
Make	: VOLKSWAGEN PASSAT	Policy No.	: SP2002150947-01
Assignment Date	: 07/02/2023	Excess	: S\$0.00
Date of Inspection	: 10/02/2023	Est. Duration of Repair	: 4
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,283.37
Revised Amount	:S\$	6,443.61
Check Items (Estimated)	:S\$	1,189.76
Total	:S\$	7,633.37

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	126,000.00
COE / PARF Rebate	:S\$	50,781.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,219.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :part by part repair as repairer is agent workshop.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.