

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SDW59M**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 20.01.2023
 TIME OF ACCIDENT : 15:00 HOURS

20	TAILGATE LOCK DETECTOR WIRE HARNESS <i>MC</i>	1	\$ 269.60	\$ 269.60	+
21	TAIL GATE LOCK BUZZER <i>Dnd</i>	1	\$ 148.60	\$ 148.60	-
22	TAILGATE ABSORBER <i>MC</i>	2	\$ 351.80	\$ 703.60	+
23	TAILGATE SIDE SENSOR <i>MC Dnd</i>	2	\$ 877.60	\$ 1,755.20	+
24	TAILGATE AUTO MOTOR <i>MC</i>	1	\$ 2,812.70	\$ 2,812.70	+
25	TAILGATE TOP LOCK <i>Dnd</i>	1	\$ 800.70	\$ 800.70	- 515.
26	TAILGATE LOWER LOCK <i>MC</i>	1	\$ 55.70	\$ 55.70	+
27	TAILGATE INNER TRIM <i>Dnd</i>	1	\$ 734.85	\$ 734.85	-
28	TAILGATE INNER SIDE TRIM <i>MC</i>	2	\$ 123.80	\$ 247.60	+
29	TAILGATE INNER HOLDER <i>Missing</i>	1	\$ 52.10	\$ 52.10	-
30	TAILGATE INNER SWITCH BUTTON <i>MC</i>	1	\$ 284.60	\$ 284.60	+
31	TAILGATE WEATHER STRIP <i>lit</i>	1	\$ 324.72	\$ 324.72	-
32	TAILGATE STOPPER <i>3pc</i>	4	\$ 25.10	\$ 100.40	+
33	TAILGATE SIDE STOPPER <i>MC</i>	2	\$ 85.00	\$ 170.00	+
34	TAILGATE SPOILER <i>MC</i>	1	\$ 963.70	\$ 963.70	+
35	TAILGATE WINDSCREEN C/W MOULDING <i>MC</i>	1	\$ 1,297.40	\$ 1,297.40	- 155.
36	REAR AIR CON BLOWER MOTOR <i>MC</i>	1	\$ 1,869.70	\$ 1,869.70	+
37	REAR FENDER INNER TRIM <i>MC</i>	2	\$ 2,024.20	\$ 4,048.40	- 1850.
38	REAR FENDER INNER COWLING <i>MC</i>	2	\$ 236.80	\$ 473.60	+
39	REAR CORNER PANEL <i>torn</i>	2	\$ 290.30	\$ 580.60	-
40	REAR CORNER PANEL RETAINER <i>MC</i>	2	\$ 98.20	\$ 196.40	+
41	TAILLAMP <i>lit</i>	2	\$ 689.20	\$ 1,378.40	-
42	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 781.10	\$ 781.10	-
43	REAR END PANEL (INNER) <i>Dented</i>	1	\$ 964.60	\$ 964.60	- 865.
44	REAR END PANEL TOP GARNISH <i>Dnd</i>	1	\$ 167.90	\$ 167.90	-
45	REAR FLOOR PANEL <i>Repair</i>	1	\$ 818.20	\$ 818.20	+
46	REAR FLOOR PANEL MAT <i>MC</i>	1	\$ 755.30	\$ 755.30	+
47	REAR FLOOR PANEL TOP BOARD (SIDE) <i>Dnd</i>	2	\$ 489.10	\$ 978.20	-
48	REAR FLOOR PANEL TOP BOARD (CENTER) <i>Dnd</i>	1	\$ 281.90	\$ 281.90	-
49	REAR FLOOR SIDE BOTTOM GARNISH LH <i>MC</i>	1	\$ 155.70	\$ 155.70	+
50	REAR FLOOR PANEL TRAY (CENTER) <i>Dnd</i>	1	\$ 358.20	\$ 358.20	-
51	REAR SEAT RAILWAY (CENTER) <i>Best</i>	2	\$ 1,230.10	\$ 2,460.20	- 1550.
52	REAR SEAT RAILWAY CENTER COVER GARNISH <i>Dnd</i>	2	\$ 209.80	\$ 419.60	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SDW59M**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 20.01.2023
 TIME OF ACCIDENT : 15:00 HOURS

53	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT	4	\$ 48.20	\$ 192.80
----	--	---	----------	-----------

18946.27
14209.70

TOTAL PRICE \$ 38,209.27
 LESS 25% \$ 9,552.32
SUB TOTAL PRICE \$ 28,656.95

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
4	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	TAILGATE INNER SIDE TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00
7	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00
8	TAILGATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 650.00	\$ 650.00
9	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
10	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
11	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
12	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
13	REAR END PANEL (INNER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
14	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
15	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00
16	REAR FLOOR PANEL MAT CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
17	REAR SEAT RAILWAY CENTER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
18	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
19	TRIANGLE BRAKEDOWN SIGN <i>could</i>	1	\$ 180.00	\$ 180.00
20	VIDEO RECORDER <i>new</i>	1	\$ 880.00	\$ 880.00
21	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00

A30

TOTAL \$ 4,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SDW59M**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 20.01.2023
 TIME OF ACCIDENT : 15:00 HOURS

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,800.00	1100
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1100
3	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 650.00	80
4	TUFF COAT	\$ 250.00	80
5	REMOVE AND REPLACE REAR WIREHARNES	\$ 480.00	x.
6	REMOVE & REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	x.
7	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	50
8	REMOVE & REFIX REVERSE CAMERA & DISTANCE SETTING	\$ 80.00	50
9	REMOVE AND REFIX REAR AIRCON BLOWER AND REFILL AIRCON GAS	\$ 350.00	x.
10	REAR CHASSIS ALIGNMENT	\$ 250.00	x
11	REMOVE AND REFIX TAILGATE SPOILER	\$ 120.00	x
12	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
13	REMOVE & REFIX VIDEO RECORDER	\$ 180.00	50
14	REMOVE & REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
15	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SDW59M**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 20.01.2023
 TIME OF ACCIDENT : 15:00 HOURS

16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	180-
----	--	-----------	------

TOTAL \$ **8,120.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 32,706.95
 TOTAL LABOUR COST : \$ 8,120.00
 TOTAL REPAIR COST : \$ 40,826.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

2890

Adrian King
 1/s 30/01/23.

07 Days.

total: 17529.7

2/s: 1HK

1HK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: