

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 30.01.2023

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SGD6421A
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 20.01.2023
TIME OF ACCIDENT : 16:00 HOURS

Xiao Tony
MRO3REH

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 571.10	\$ 571.10
2	REAR BUMPER REFLECTOR <i>Left LH c/w</i>	2	\$ 79.20	\$ 158.40
3	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 105.10	\$ 210.20
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 460.10	\$ 460.10
5	BOOTLID <i>Cracked</i>	1	\$ 793.10	\$ 793.10
6	BOOTLID LAMP <i>LH w</i>	2	\$ 342.00	\$ 684.00
7	BOOTLID OUTER MOULDING (CHROME) <i>new</i>	1	\$ 426.00	\$ 426.00
8	BOOTLID DETECTOR <i>Dented</i>	1	\$ 385.00	\$ 385.00
9	BOOTLID LOGO <i>?</i>	1	\$ 85.00	\$ 85.00
10	BOOTLID EMBLEM 'COROLLA' <i>new</i>	1	\$ 70.00	\$ 70.00
11	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00
12	BOOTLID STOPPER <i>new</i>	2	\$ 28.00	\$ 56.00
13	BOOTLID TOP LOCK <i>Dented</i>	1	\$ 379.40	\$ 379.40
14	BOOTLID LOWER LOCK <i>new</i>	1	\$ 20.00	\$ 20.00
15	BOOTLID WEATHERSTRIP <i>lt</i>	1	\$ 195.00	\$ 195.00
16	TAILLAMP <i>LH c/w</i>	2	\$ 465.00	\$ 930.00
17	TAILLAMP LOWER BARCKET <i>new</i>	2	\$ 115.10	\$ 230.20
18	REAR FENDER INNER COWLING <i>3 x 1</i>	2	\$ 350.20	\$ 700.40
19	REAR FENDER INNER TRIM <i>new</i>	2	\$ 770.10	\$ 1,540.20
20	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30

✓
+ 79.20
+
395
342
+
185
✓
✓
+
+
+
465
+
+
+
✓

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGD6421A
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 20.01.2023
 TIME OF ACCIDENT : 16:00 HOURS

21	REAR END PANEL TOP GARNISH <i>Delnd</i>	1	\$ 250.10	\$ 250.10	-
22	REAR FLOOR PANEL TOP BOARD <i>Delnd</i>	1	\$ 271.10	\$ 271.10	-
23	REVERSE SENSOR <i>Delnd</i>	2	\$ 356.70	\$ 713.40	500
24	REVERSE SENSOR HOLDER <i>New</i>	2	\$ 69.30	\$ 138.60	X.
25	REVERSE SENSOR WIREHARNES <i>New</i>	1	\$ 437.50	\$ 437.50	X.

5356.30 TOTAL PRICE \$ 11,349.40
 LESS 25% \$ 2,837.35
 4017.22 SUB TOTAL PRICE \$ 8,512.05

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>New</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	BOOTLID SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	X.
4	BOOTLID OUTER MOULDING (CHROME) CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
5	BOOT LID INSULATOR CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
6	TAILLAMP CLIPS (SET) <i>m</i>	1	\$ 30.00	\$ 30.00	20
7	REAR FENDER COWLING CLIPS (SET) <i>2 m</i>	1	\$ 80.00	\$ 80.00	X
8	REAR FENDER INNER TRIM CLIP (SET) <i>1 New</i>	1	\$ 80.00	\$ 80.00	X.
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>m</i>	1	\$ 50.00	\$ 50.00	20
10	REAR END PANEL INSULATION SEAL <i>m</i>	1	\$ 150.00	\$ 150.00	60
11	BREAKDOWN TRIANGLE SIGN <i>New</i>	1	\$ 180.00	\$ 180.00	X.
12	REVERSE CAMERA <i>Delnd</i>	1	\$ 550.00	\$ 550.00	380

500

TOTAL \$ 1,010.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGD6421A
 MODEL : TOYOTA COROLLA ALTIS
 DATE OF ACCIDENT : 20.01.2023
 TIME OF ACCIDENT : 16:00 HOURS

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	60.
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X

TOTAL \$ 4,800.00

TOTAL PARTS COST : \$ 9,522.05
 TOTAL LABOUR COST : \$ 4,800.00
 TOTAL REPAIR COST : \$ 14,572.05

1910

Adnan
 1/2 31/01/23.

06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 6427.22

4/5: 5.1k. ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: