

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Xiao Terry

Quotation

DATE : 25.01.2023
 VEH NO : SGN4461U
 MODEL : Hyundai Elantra
 D O A : 24.01.2023
 YR REF : SFA1499L

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGN4461U (HYUNDAI ELANTRA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Distorted</i>	1	474.40 ✓
2	Front Bumper Side Holder - LH <i>Dented</i>	1	35.40 ✓
3	Front Bumper Fog Lamp - LH <i>new</i>	1	298.40 ✗
4	Front Bumper Fog Lamp Cover - LH <i>new</i>	1	105.20 ✗
5	Front Bumper Inner Air Duct - LH <i>Del'd</i>	1	158.10 ✓
6	Front Grille <i>new</i>	1	460.20 ✗
7	Front Grille Logo <i>new</i>	1	52.40 ✗
8	Head Lamp - LH <i>cracked</i>	1	1,248.60 ✓
9	Head Lamp Lower Bracket - LH <i>cracked</i>	1	145.70 ✓
10	Front Support Panel <i>cracked</i>	1	987.50 ✓
11	Front Fender - LH <i>Distorted</i>	1	1,227.00 ✓
12	Front Fender Inner Shield - LH <i>Del'd</i>	1	145.90 ✓
13	Front Fender Inner Enclosure - LH <i>Del'd</i>	1	34.90 ✓
14	Front Fender Mudflap - LH <i>cracked</i>	1	49.60 ✓
15	Front Door - LH <i>Dented</i>	1	1,832.40 ✓
16	Front Door Lock - LH <i>new</i>	1	247.20 ✗
17	Front Door Weatherstripe - LH <i>new</i>	1	135.80 ✗
18	Front Door Hinge - LH <i>new</i>	1	110.20 ✗
19	Front Door Check - LH <i>new</i>	1	49.40 ✗
20	Front Door Inner Trimboard - LH <i>cracked</i>	1	627.80 ✓
21	Front Door Glass Regulator Gear - LH <i>new</i>	1	223.40 ✗
22	Front Door Glass Regulator Motor - LH <i>new</i>	1	388.50 ✗
23	Rocker Panel - LH <i>Dented</i>	1	623.90 ✓
24	Rear Door - LH <i>Dented</i>	1	1,879.20 ✓
25	Rear Door Lock <i>new</i>	1	265.40 ✗
26	Rear Door Weatherstripe <i>new</i>	1	159.40 ✗
27	Rear Door Inner Trimboard - LH <i>cracked</i>	1	658.20 ✓
28	Rear Door Glass Regulator Gear - LH <i>new</i>	1	251.40 ✗

RE : ESTIMATE FOR ACCIDENT REPAIR SGN4461U (HYUNDAI ELANTRA)

29	Rear Door Glass Regulator Motor - LH <i>new</i>	1	381.40 <i>x</i>
30	Front Lower Arm <i>But</i>	1	326.70 <i>-</i>
31	Front Knuckle Arm <i>new</i>	1	451.30 <i>-</i>
32	Front Shock Absorber <i>But</i>	1	263.10 <i>-</i>
33	Front Wheel Hub c/w Bearing <i>new</i>	1	266.00 <i>-</i>

11435.70

9148.56

Less 20%

14,564.00

(2,912.80)

\$ 11,651.20

S/NETT ITEMS

1	Front Bumper Clips <i>new</i>	1 set	\$ 30.00 <i>-</i>
2	Front Grille Clips <i>new</i>	1 set	\$ 20.00 <i>x</i>
3	Front Fender Inner Shield Clips - LH <i>new</i>	1 set	\$ 30.00 <i>-</i>
4	Front Door Inner Trimboard Clips - LH <i>new</i>	1 set	\$ 30.00 <i>-</i>
5	Front Door Black Tape - LH <i>new</i>	1	\$ 60.00 <i>-</i>
6	Rear Door Inner Trimboard Clips - LH <i>new</i>	1 set	\$ 30.00 <i>-</i>
7	Rear Door Black Tape - LH <i>new</i>	1	\$ 60.00 <i>-</i>
8	Front Wheel Rim - LH <i>new</i>	1	\$ 850.00 580 <i>x</i>
9	Front Tyre - LH <i>new</i>	1	\$ 250.00 <i>x</i>
10	Coolant <i>new</i>	1	\$ 50.00 <i>-</i>

Total Parts

\$ 13,061.20

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 1,600.00 <i>1400</i>
2	To putty & spray up paint works	\$ 1,400.00 <i>1000</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To apply tuff coat	\$ 150.00 <i>100</i>
5	To transfer front & rear door fittings	\$ 300.00 <i>160</i>
6	To remove condenser & top-up aircon gas	\$ 120.00 <i>60</i>
7	To remove radiator & top-up coolant	\$ 120.00 <i>60</i>
8	To dismantle front undercarriage	\$ 350.00 <i>220</i>
9	To perform wheel alignment	\$ 150.00 <i>80</i>

Total Labour

\$ 4,240.00

Grand Total

\$ 17,301.20

RE : ESTIMATE FOR ACCIDENT REPAIR SGN4461U (HYUNDAI ELANTRA)

NOTE : -

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

total: 13128.56.

L/S : 10.5K.

12 Days.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: