## **CITYCAB PTE LTD**

## REPAIR ESTIMATE\*

**VEHICLE NO** 

MODEL

SHC436R

MAKE REG.02.04.2019

IONIQ G2

07.02.2023

CHIANG/ALLIANZ

Qty	Parts Description/ Labour	Туре			Amount	7
	1 REAR BUMPER 505				\$459.40	
-	1 REAR BUMPER SIDE BRACKET RH ?	1		\$55.80	\$55.80	1
	1 REAR BUMPER CENTRE MOULDING 🐉 S 🗸				\$451.25	
:	1 REAR BUMPER REINFORCEMENT ?				\$394.80	all a
2	REAR BUMPER REINFORCEMENT STAY RH 🕺 🖊			\$138.10	\$138.10	1
	REAR BUMPER FOG LAMP ?				\$201.50	1
1	TOWING COVER X W W		O + m		\$98.80	
10	REAR BUMPER CLIPS × 1∪ ~ /	122	80	\$2.20	\$22.00	1
	SUB_TOTAL	11.5			\$1,821.65	
	20.00%	9			\$364.33	
	DISCOUNTED TOTAL	142	80	Ī	\$1,457.32	1
	. /	110	7			1
1	REAR BUMPER MAT WEC				\$50.00	
1	REAR NUMBER PLATE W/HOLDER \$\( \sigma \)		(7)		\$55.00	4 _
1	REAR REVERSE SENSOR ?	2011	50	× [	\$180.00	_
					\$261.50	
						l l
	Labour Charge					
	Panel Beating	LOU			\$550.00	35
	Spray Painting Charge	00			\$300.00	
	Tuff Kote	6			\$60.00	
	Remove/refix Reverse sensor				\$60.00	
	TOTAL LABOUR		-		\$970.00	
		2779	18			
	ESTIMATE TOTAL	100	7		\$2,688.82	
					1200	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will					
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

20/01

2 drys

115

5/2/03