

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305544966
Date : 08.02.23
Time of Fax : -

Via Fax : EMAIL
Your Insured : GBF9285E
Date of Acc : 07.02.23

Attn: Motor Claims Department

Allianz

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C 436R

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

| | |
|----------------------------|--|
| ◆ Lim Kwok Eng | Tel: 6214 8355 or HP: 9824 0811 |
| ◆ Jumani Bin Masudin | Tel: 6214 8315 or HP: 9635 5305 |
| ◆ Lim Tien Siong | Tel: 6214 8398 or HP: 9635 8546 |
| ◆ <u>Chiang Liat Choon</u> | <u>Tel: 6214 8314 or HP: 9296 6006</u> |

} chianglc@cdge.com.sg
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully


For Vice President
Taxi Accident Repair

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC436R

07.02.2023

MAKE REG.02.04.2019

CHIANG/ALLIANZ

MODEL IONIQ G2

| Qty | Parts Description/ Labour | Type | Amount |
|--|-----------------------------------|------|-------------------|
| 1 | REAR BUMPER | | \$459.40 |
| 1 | REAR BUMPER SIDE BRACKET RH | | \$55.80 |
| 1 | REAR BUMPER CENTRE MOULDING | | \$451.25 |
| 1 | REAR BUMPER REINFORCEMENT | | \$394.80 |
| 2 | REAR BUMPER REINFORCEMENT STAY RH | | \$138.10 |
| 1 | REAR BUMPER FOG LAMP | | \$201.50 |
| 1 | TOWING COVER | | \$98.80 |
| 10 | REAR BUMPER CLIPS | | \$22.00 |
| | SUB TOTAL | | \$1,821.65 |
| | 20.00% | | \$364.33 |
| | DISCOUNTED TOTAL | | \$1,457.32 |
| 1 | REAR BUMPER MAT | | \$50.00 |
| 1 | REAR NUMBER PLATE W/HOLDER | | \$55.00 |
| 1 | REAR REVERSE SENSOR | | \$180.00 |
| | | | \$261.50 |
| | | | |
| | Labour Charge | | |
| | Panel Beating | | \$550.00 |
| | Spray Painting Charge | | \$300.00 |
| | Tuff Kote | | \$60.00 |
| | Remove/refix Reverse sensor | | \$60.00 |
| | TOTAL LABOUR | | \$970.00 |
| | | | |
| | ESTIMATE TOTAL | | \$2,688.82 |
| | | | |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will | | | |
| be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | |