

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD391E

Not Notarised
 1/1mp \$6900p Max
 Reusing After Paint

AAD2302-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 FEB 2023

SHD391E

VF1ABL15AUC283416

200303878K

RENAULT

LATITUDE

03/02/2023

SMF2992M/AIG-

30/09/2016

PART**LIST**

1 BUMPER COVER REAR	\$	Bz	561.70	✓
1 BUMPER LOWER REAR	\$	Bz	411.90	✓
1 BUMPER REFLECTOR RH	\$	CMT	16.60	✓
1 BUMPER REFLECTOR LH	\$	Sn	16.60	X
1 BUMPER BRACKET CTR REAR	\$	DTI	98.10	✓
1 BUMPER BRACKET SIDE RH REAR	\$	Sn	82.10	X
1 BUMPER RETAINER RH REAR	\$	Sn	59.80	X
1 BUMPER BRACKET SIDE LH REAR	\$	Sn	80.80	X
1 BUMPER RETAINER LH REAR	\$	Sn	54.20	X
1 FENDER PANEL REAR RH	\$	R	1,933.20	X
1 WHEELARCH REAR RH	\$	Sn	275.40	X
1 BUMPER BEAM REAR	\$	Bz	547.80	✓
1 BUMPER BEAM BRACKET LH REAR	\$	R	114.50	X
1 BUMPER BEAM BRACKET RH REAR	\$	R	114.50	X
1 OUTER PANEL REAR (End Panel)	\$	Bz	745.80	✓
1 OUTER PANEL REAR (End Panel)TRIM	\$	R	404.56	✓
1 BOOT REAR	\$	Bz	1,677.20	✓
1 BOOT LOCK	\$	R	246.60	✓
1 BOOT LOCK CATCH	\$	R	41.70	X
1 BOOT FINISHER	\$	Sn	344.70	X
1 BOOT WEATHERSTRIP	\$	W	178.20	50 pps 89.40 pps
1 BOOT STRUT LH	\$	Sn	145.10	X
1 BOOT STRUT RH	\$	Sn	145.10	X
1 BOOT HINGE LH	\$	R	254.20	X
1 BOOT HINGE RH	\$	R	254.20	X
1 BOOT BADGE 'RENAULT'	\$	R	82.40	✓

Trans-cab Auto Services Pte Ltd

AAD2302-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD391E

- 1 BOOT BADGE
- 1 BUMPER COVER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BRACKET KIT FRT LH
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER BRACKET KIT FRT RH
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE BADGE 'RENAULT'
- 1 RADIATOR GRILLE FRAME
- 1 FRAME FULL SUPPORT PANEL
- 1 HEADLAMP LH
- 1 HEADLAMP RH

\$	<i>na</i>	95.80	✓
\$	<i>Bu</i>	747.20	✓
\$	<i>sn</i>	394.68	X
\$	<i>sn</i>	101.40	X
\$	<i>Dis sn</i>	101.40	✓
\$	<i>sn</i>	101.40	X
\$	<i>sn</i>	101.40	X
\$	<i>sn</i>	10.70	X
\$	<i>sn</i>	147.00	X
\$	<i>sn</i>	207.21	X
\$	<i>sn</i>	207.21	X
\$	<i>CM</i>	969.90	✓
\$	<i>na</i>	225.36	✓
\$	<i>sn</i>	686.00	X
\$	<i>sn</i>	592.70	X
\$	<i>ng cm</i>	743.60	✓
\$	<i>" "</i>	743.60	✓
\$		15,063.52	
10%	\$	1,506.35	
\$		13,557.17	

Specical Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR CLIP
- 1 REAR BOOT STICKER 'Trans-cab'
- 1 REAR BOOT STICKER '6555-3333'
- 1 FRONT BUMPER CLIP
- 1 LICENSE PLATE WITH HOLDER REAR
- 2 LICENSE PLATE WITH HOLDER FRT
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>sn</i>	700.00	X
\$	<i>na</i>	66.00	✓
\$	<i>na</i>	10.00	X
\$	<i>na</i>	20.00	X
\$	<i>na</i>	10.00	X
\$	<i>na</i>	20.00	X
\$	<i>na</i>	66.00	✓
\$	<i>na</i>	80.00	30sn
\$	<i>na</i>	80.00	30sn
\$	<i>na</i>	66.00	✓
\$	<i>sn</i>	120.00	X
\$	<i>As</i>	121.00	45sn
\$	<i>na</i>	150.00	X
\$	<i>na</i>	200.00	X
\$	<i>na</i>	130.00	X
TOTAL	\$	1,839.00	

Trans-cab Auto Services Pte Ltd

AAD2302-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD391E

TOTAL PARTS	\$	15,396.17
--------------------	-----------	------------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>8001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>601</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD391E

AAD2302-

TOTAL \$ 7,880.00

Over All Total \$ 36,833.33

(LUMP SUM)

Repair Days

12 DAYS

6 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: