



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--|----------------------------|------------|
| LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428 | | | Ref: CS/LIP23001347/Avy3m4 | |
| | | | Date: 16/06/2023 | |
| | | | Code: LIP | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | XD 9027J | Veh. Inspected | SMJ 9889L |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | AVS23/0490 | Excess (\$) | 0.00 |
| | Assign From | ANDY SEAH | Assign Date | 08/02/2023 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | mitsubishi attrage | c.c | 1193 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | MMBSTA13AKH001230 | Colour | SILVER |
| | Odometer | 70290 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195/55R15 | TOURADOR | 6 mm |
| | L/H Front Tyre | 195/55R15 | TOURADOR | 6 mm |
| | R/H Rear Tyre | 195/55R15 | TOURADOR | 6 mm |
| | L/H Rear Tyre | 195/55R15 | TOURADOR | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 06/02/2023 | Inspection Date | 08/02/2023 |
| | Survey held at | UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883 | | |
| 5a. Remarks | | | | |
| | A)REGISTRATION DATE: 21 FEB 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 12 Working Days | |