



AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

TP Liberty

LKK

DATE: 16/02/2023

OUR REF: UAPL1578

DATE: 16/02/2023 OUR REF: OAPET1570
REPAIR ESTIMATE TO THE MIT-ATRAGE NO: SMJ9889L

REAR ITEM

REAR ITEM

- 1 REAR BOOT ASSY Distorted
- 2 REAR BOOT HINGES Dist
- 1 REAR BOOT LOCK Dist
- 1 REAR BOOT LOCK STRIKER Dist
- 1 REAR BOOT WEATHERSTRIP Dist
- 1 REAR BOOT OUTER CHROME STRIP Dist
- 1 REAR BOOT EMBLEM Dist
- 1 REAR BOOT (ATTRAGE) EMBLEM Dist
- 1 REAR BOOT (MIVEC) EMBLEM Dist
- 2 REAR TAILLAMP ASSY Dist
- 2 REAR TAILLAMP SIDE CLIPS Dist
- 2 REAR TAILLAMP PANEL Dist
- 1 REAR TAIL END PANEL Distorted
- 1 REAR TAIL END PANEL AIR DUCT (INNER) Distorted
- 1 REAR TAIL END PANEL AIR DUCT (OUTER) Distorted
- 1 REAR TAIL END PANEL INNER GARNISH Distorted
- 1 REAR SMART KEYLESS SENSOR Dist
- 1 REAR KEYLESS SENSOR JOINT UNIT Dist
- 1 REAR BUMPER FACE Distorted
- 2 REAR BUMPER SIDE RETAINERS Dist
- 1 REAR BUMPER CLIPS (1 SET) Dist
- 2 REAR BUMPER LOWER RELETOR Dist
- 1 REAR L/H FENDER ASSY Distorted
- 1 REAR R/H FENDER ASSY Distorted
- 2 REAR FENDER TOP SIDE PANEL Dist
- 2 REAR FENDER INNER SIDE GARNISH Distorted
- 2 REAR NUMBER PLATE LAMP ASSY Dist
- 2 REAR MUD GUARD GARNISH Dist
- 1 REAR WINDSCREEN MOULDING Dist
- 1 REAR SPARE TYRE TOP COVER Dist
- 1 REAR FLOOR PANEL Dist
- 2 REAR EXHAUST BOX RUBBER HOLDER Dist

LESS 10%.

SPECIAL NETT:-

SPECIAL NETT:-

1 REAR PUMPER LOWER SPOILER	Distorted
1 REAR BOOT TOP SPOILER	Crushed
1 SET REAR REVERSE SENSOR	None
1 REAR WINDSCREEN GLASS RUBBER GUM	None
1 REAR NUMBER PLATE	Best
1 REAR REVERSE CAMERA UNIT	Crushed
1 REAR BOOT RUBBER TRAY	Not used
1 REAR SEAT BACK COVER GARNISH	Not used

LABOUR CHARGES:-

TO TOW VEHICLE TO WORKSHOP
TO DISM/REFIX REAR WINDSCREEN GLASS
TO SPRAY UNDERCOATING IN REPAIR
TO DISM/REWIRE DAMAGED PORTION
TO DISM/RENEW REAR REVERSE SENSOR/ CAMERA
TO DISM/REFIX ROOF LINING SEAT/ GARNISH IN REPAIR
TO DISM/RENEW REAR EXHAUST PIPE
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
TO PUTTY AND RESPRAY DAMAGED PORTION

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	948.00	✓	828
\$	384.00	✓	196
\$	216.00	✓	
\$	58.00	+	
\$	212.00	✓	
\$	258.00	✓	
\$	61.00	✓	
\$	74.00	✓	
\$	58.00	✓	
\$	790.00	✓	670
\$	28.00	✓	
\$	422.00	✓	
\$	515.00	✓	
\$	98.00	✓	45
\$	98.00	✓	40
\$	187.00	✓	
\$	223.00	✓	91
\$	211.00	✓	965
\$	865.00	✓	765
\$	72.00	✓	
\$	55.00	✓	30
\$	118.00	X	
\$	913.00	✓	855
\$	913.00	✓	855
\$	230.00	+	
\$	442.00	✓	
\$	142.00	X	
\$	104.00	+	
\$	187.00	✓	
\$	255.00	✓	195
\$	966.00	X	
\$	56.00	X	
\$	10,159.00		
\$	1,015.90		
\$	9,143.10		

\$	1200.00	800
\$	800.00	550
\$	280.00	200
\$	60.00	60.
\$	50.00	✓
\$	220.00	✓
\$	150.00	x
\$	120.00	x

\$	100.00	60
\$	<u>220.00</u>	120
\$	<u>380.00</u>	100
\$	<u>280.00</u>	300
\$	<u>180.00</u>	100
\$	<u>280.00</u>	60
\$	<u>120.00</u>	X
\$	<u>3,000.00</u>	1800
\$	<u>1,800.00</u>	1600
\$	<u>18,383.10</u>	

Veren

7388

6658.20.

1880

3870

total: 12428.20
r/s: 9.91c.

12 Days