



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23001349/Tqy3m4 Date: 19/04/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 1596B	Veh. Inspected	SMJ 9637Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/02/23/5010/KC	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	08/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VELLFIRE	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	AGH300221317	Colour	BLACK
	Odometer	184138 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/45 R19	HABILEAD	6 mm
	L/H Front Tyre	245/45 R19	HABILEAD	6 mm
	R/H Rear Tyre	245/45 R19	HABILEAD	6 mm
	L/H Rear Tyre	245/45 R19	HABILEAD	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/02/2023	Inspection Date	08/02/2023
	Survey held at	LIM MOTOR PTE LTD 160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	