



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23001351/Uqy3q2	
			Date: 16/02/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 9808J	Veh. Inspected	SDA 6655T	
Policy No.	D22MTPV01003833	Coverage (\$)	0.00	
Claim No.	CMTD2300355/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	08/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC200 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDC2539422F391761	Colour	BLACK	
Odometer	48357 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	MICHELIN	7 mm	
L/H Front Tyre	235/55 R19	MICHELIN	7 mm	
R/H Rear Tyre	235/55 R19	MICHELIN	7 mm	
L/H Rear Tyre	235/55 R19	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/01/2023	Inspection Date	08/02/2023	
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	