

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0133/2023/EQ
DATE : 03-Feb-23
WIP : 60894

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
5 days & 1 Sunday
Johnny Boo 28 Mar 23*

OWNER'S NAME : MS CHEE OI CHOO
ADDRESS : 9 BUKIT BATOK CENTRAL LINK
#10-05
SINGAPORE 658074
TELEPHONE : HP +65 98338807
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100429549-07
VEHICLE NO : **SCV 1312 S**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TF
MODEL YEAR : 23/09/2015
ENGINE NO : CZC 283157
CHASSIS NO : WAUZZZ8V9GA034778
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jan-23
PLACE OF ACCIDENT : BLK 18 CAR PARK Ngee Ann Polytechnic 535 CLEMENTI ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCV 1312 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$ 1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,282.00	\$ 2,542.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCV 1312 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,273.00	\$ 1,818.40
2	FRONT BUMPER FIXING PARTS	1	\$ 207.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 185.00	
4	FRONT BUMPER GUIDE SECTION - RH	1	\$ 75.00	\$ 59.92
5	FRONT BUMPER AIR GUIDE GRILLE- RH	1	\$ 129.00	
6	FRONT FENDER - RH	1	\$ 1,012.00	\$ 809.60
7	FRONT FENDER ATTACHMENT PARTS	1	\$ 80.00	
8	FRONT FENDER CLOSING ELEMENT	1	\$ 73.00	\$ 57.68
9	FRONT FENDER BRACKET - RH	1	\$ 72.00	
10	FRONT FENDER RIVET	9	\$ 36.00	\$ 28.80
11	FRONT FENDER BRACE	1	\$ 114.00	\$ 91.20
12	FRONT WHEEL HOUSING LINER	1	\$ 198.00	\$ 158.00
13	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 99.00	
14	HEADLIGHT GAS DISCHARGE LAMP - RH	1	\$ 2,975.00	\$ 2,380.00
15	HEADLIGHT POWER MODULE	1	\$ 690.00	
16	HEADLIGHT CONTROL UNIT	1	\$ 1,390.00	
17	GAS DISCHARGE LAMP	1	\$ 462.00	
18	HEADLIGHT HOSE - RH	1	\$ 62.00	
19	LIFT CYLINDER - RH	1	\$ 223.00	
20	LIFT CYLINDER HOSE	1	\$ 208.00	
SUB TOTAL SPARE PARTS		:	\$ 10,563.00	\$ 5,403.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCV 1312 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 5,403.60
21	FRONT ALUMINIUM RIM	1 \$	1,411.00	
22	FRONT ALUMINIUM RIM RUBBER VALVE	1 \$	4.00	
23	SUNDRIES	\$	400.00	\$ 7.60
TOTAL SPARE PARTS		:	\$ 12,378.00	\$ 5,411.20
TOTAL LABOUR CHARGES		:	\$ 5,282.00	\$ 2,542.00
GRAND TOTAL		:	\$ 17,660.00	\$ 7,953.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-25/03/23