

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0133/2023/EQ
DATE : 3-Feb-23
WIP : 60894

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHEE OI CHOO
ADDRESS : 9 BUKIT BATOK CENTRAL LINK
#10-05
SINGAPORE 658074
TELEPHONE : HP +65 98338807
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100429549-07
VEHICLE NO : **SCV 1312 S**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TF
MODEL YEAR : 23/9/2015
ENGINE NO : CZC 283157
CHASSIS NO : WAUZZZ8V9GA034778
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jan-23
PLACE OF ACCIDENT : BLK 18 CAR PARK Ngee Ann Polytechnic 535 Clementi Road

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCV 1312 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	x x
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000 ✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	1100 ✓
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	x x
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ J
TOTAL LABOUR CHARGES		:	\$ 5,282.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCV 1312 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Debond</i>	1	\$ 2,273.00	✓ 1818.4
2	FRONT BUMPER FIXING PARTS <i>Not new</i>	1	\$ 207.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not new</i>	1	\$ 185.00	+
④	FRONT BUMPER GUIDE SECTION - RH <i>Damaged.</i>	1	\$ 75.00	✓ 59.92
5	FRONT BUMPER AIR GUIDE GRILLE- RH <i>Not new</i>	1	\$ 129.00	+
6	FRONT FENDER - RH <i>Debond</i>	1	\$ 1,012.00	✓ 809.6
7	FRONT FENDER ATTACHMENT PARTS <i>Not new</i>	1	\$ 80.00	+
⑧	FRONT FENDER CLOSING ELEMENT <i>Damaged.</i>	1	\$ 73.00	✓ 57.68
⑨	FRONT FENDER BRACKET - RH <i>Not new</i>	1	\$ 72.00	X
⑩	FRONT FENDER RIVET <i>Not new</i>	9	\$ 36.00	✓ 28.8
⑪	FRONT FENDER BRACE <i>Best</i>	1	\$ 114.00	✓ 91.20
⑫	FRONT WHEEL HOUSING LINER <i>Debond.</i>	1	\$ 198.00	✓ 158
13	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not new</i>	1	\$ 99.00	+
14	HEADLIGHT GAS DISCHARGE LAMP - RH <i>cracked</i>	1	\$ 2,975.00	✓ 2380
15	HEADLIGHT POWER MODULE <i>Not new</i>	1	\$ 690.00	+
16	HEADLIGHT CONTROL UNIT	1	\$ 1,390.00	+
17	GAS DISCHARGE LAMP <i>Not new</i>	1	\$ 462.00	+
18	HEADLIGHT HOSE - RH	1	\$ 62.00	+
⑲	LIFT CYLINDER - RH <i>Not new</i>	1	\$ 223.00	X
20	LIFT CYLINDER HOSE <i>Not new</i>	1	\$ 208.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,563.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCV 1312 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT ALUMINIUM RIM	1	\$ 1,411.00	x
22	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	x
23	SUNDRIES		\$ 400.00	✓ 7.60
TOTAL SPARE PARTS		:	\$ 12,378.00	
TOTAL LABOUR CHARGES		:	\$ 5,282.00	
GRAND TOTAL		:	\$ 17,660.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *07/02/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 07 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT