

(08/11/13) wef

ISS. REC. BY: Marcus

REF:

CC4/LPC 23001354/423

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL59218M

at Workshop m/s

H.

of

Insured:

YF8534K

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

469k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

828h
Vehicle: IN / OUT
LTA 29915

Veh No:

SL59218M

Yr Regn:

11/10/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Qashqai c.c

1197

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

92409

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SJNFEA J114 2000213

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/10/23

D.O.I.

09/11/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & L.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/11/23 Tailgate 83366 have G.A
4/5 & 10 SW in hand ALEN.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorised
Her
9/2/23
2/5 = 10,500
6 days

VEHICLE No: SLS 9218M

NETT ITEM

1PC	REAR WINDSCREEN	11		\$1,288.20	X
1PC	REAR WINDSCREEN MOULDING	1er		\$145.80	/
1PC	TAILGATE	11	3366.20	\$3,466.20	/
1PC	TAILGATE OUTER HANDLE	one	308.00	\$450.00	/
1PC	TAILGATE REAR LOGO	1er		\$65.00	/
1PC	TAILGATE 'QASHQAI' EMBLEM	1er		\$85.00	/
2PCS	TAILGATE REFLECTORS @\$480.00	one	373.80 x 2 = 747.60	\$960.00	/
1PC	TAILGATE REAR WIPER ARM	11		\$166.00	X
1PC	TAILGATE REAR WIPER MOTOR	11		\$682.00	X
1PC	TAILGATE INNER LOCK	11 / JM	205.50	\$292.00	/
1PC	TAILGATE INNER TRIM BOARD	De torn	348.20	\$595.60	/
1SET	TAILGATE INNER TRIM BOARD CLIPS	1er		\$45.00	/
1PC	TAILGATE WEATHERSTRIP	11	204.60	\$265.00	/
1SET	TAILGATE REVERSE CAMERA	11		\$580.00	X
1PC	REAR BUMPER	11 / 12	946.50	\$991.00	/
1PC	REAR BUMPER TOW COVER	11		\$85.00	X
2PCS	REAR BUMPER REFLECTORS @\$85.00	one		\$170.00	/
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	1er		\$130.00	/
1SET	REAR BUMPER CLIPS	1er		\$45.00	/
1PC	REAR BUMPER SPONGE	11	168.10	\$225.00	/
1PC	REAR BUMPER BEAM	1er	246	\$721.00	/
2PCS	REAR BUMPER BEAM BRACKETS @\$150.00	1er	424	\$300.00	/
1PC	REAR END PANEL	11	573.80	\$720.00	/
1PC	REAR END PANEL LOCK SENSOR	11		\$122.00	X
1PC	REAR END PANEL TOP GARNISH	11	281.20	\$480.00	/
1PC	REAR FLOOR PANEL	11		\$1,280.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$650.00	X
1PC	REAR FLOOR PANEL TOOLS SPONGE	11		\$610.00	X
2PCS	REAR FENDERS @\$1150.00	R.		\$2,230.00	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$455.00	11		\$910.00	X
2PCS	REAR FENDER OUTER PROTECTORS @\$541.00	0/5 torn	480	\$1,082.00	1PC
2PCS	REAR FENDER UNDER TRIMS @\$350.00	11		\$700.00	X
2PCS	TAILLAMPS @\$680.00	11		\$1,360.00	X
1PC	REAR EXHAUST	11		\$1,122.20	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$315.00	X
2PCS	REAR EXHAUST MOUNTINGS @\$60.00	11		\$120.00	X
1PC	FRONT BUMPER	De	933.20	\$981.00	/
1PC	FRONT BUMPER LOWER CENTRE GRILLE	11		\$122.10	X
2PCS	FRONT BUMPER SIDE RETAINERS @\$65.00	11		\$130.00	X
1PC	FRONT BUMPER SPONGE	11		\$185.30	/
1PC	FRONT BUMPER REINFORCEMENT	R		\$715.00	X

1PC	FRONT BUMPER CENTRE GARNISH	one	\$245.00
1SET	FRONT BUMPER CLIPS	one	\$45.00
1PC	FRONT GRILLE	one	\$850.00
1SET	FRONT GRILLE CLIPS	one	\$20.00
2PCS	HEADLAMPS @\$1998.00	one	\$3,996.00
			\$30,743.40

715.20

(102)

1SET	REAR BUMPER REVERSE SENSOR	shunt	\$280.00	200
1PC	REAR WINDSCREEN SEALANT	one	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	one	\$50.00	40
1PC	REAR WINDSCREEN SOLAR FILM	one	\$250.00	X
1SET	REAR REVERSE CAMERA	one	\$380.00	X
1PC	REAR END PANEL SEALANT	one	\$50.00	✓
1PC	REAR LICENCE PLATE	one	\$50.00	X
1SET	REAR FLOOR PANEL INSULATOR	one	\$280.00	X
1PC	FRONT LICENCE PLATE	one	\$50.00	40
TO CHECK WIRING			\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR			\$80.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN			\$150.00	120
TO TRANSFER TAILGATE MECHANISM			\$100.00	60
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY			\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST			\$100.00	X
TO DISMANTLE & REFIX FUEL TANK			\$100.00	X
TO REFILL AIR CON GAS			\$120.00	X
TO SPRAY RUST PROOFING			\$150.00	60
TO RESET & REPROGRAMME SYSTEM			\$180.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$2,200.00	900
TO PUTTY & SPRAY PAINTING			\$2,200.00	1200
TOTAL			\$45,022.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

11460.2
102
10314.18
370
2490
13174.18
10539