

(08/11/13) web

ASS - REC. BY: JamesREF: CC4/11823001357/Rpa3

106P

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL2 4321Tat Workshop m/s MOVAof 1008, BUKIT MURAH W3 # 01-04Insured: AIS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 72K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL2 4321T Yr Regn: 2018 1 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai ELANTRA 1.6 GLS AT c.c. 1591Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 112063 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH0841 CMJU 688035Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: "BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 03/02/23D.O.I. 08/03/23

Survey held at

MOVADes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 44K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$)



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 169722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (440)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/02/2023
Vehicle Reg. No.:	SLZ4321T	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	03/05/2018
Vehicle Colour:	SILVER		
Engine No:	G4FGJU188498	Chassis No:	KMHD841CMJU688035
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	4,372.80
Miscellaneous Items	0.00
Labour	1,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	6,332.80
+ GST 8.00% (\$\$)	506.62
Nett Amount (\$\$)	6,839.42

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Feb 2023)
 as: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 bour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLZ4321T)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>bt</i>	0.00	0.00	*750.00 F
2	1		*BONNET STICKER <i>bt</i>	0	0.00	<i>30 30 X</i> *50.00 FS
3	1		*BONNET TRIM <i>bt</i>	0	0.00	<i>30</i> *40.00 FS
4	1		*HEADLAMP ASSY RH <i>bt</i>	0.00	0.00	*550.00 F
5	1		*HEADLAMP LOWER BRACKET RH <i>bt</i>	0.00	0.00	*25.00 F
6	1		*WASHER TANK <i>bt</i>	0.00	0.00	*95.00 F
7	1		*FRONT BUMPER <i>bt</i>	0.00	0.00	*400.00 F
8	1		*FRONT BUMPER RETAINER RH <i>bt</i>	0.00	0.00	*18.00 F
9	10		*FRONT BUMPER CLIPS <i>bt</i>	0.00	0.00	*20.00 F
10	1		*FRONT BUMPER GRILLE RH <i>bt</i>	0.00	0.00	*30.00 F
11	1		*FRONT BUMPER AIR DUCT RH <i>bt</i>	0.00	0.00	*25.00 F
12	1		*FRONT BUMPER TRIM <i>bt</i>	0	0.00	*45.00 FS
13	1		*SUPPORT PANEL <i>bt</i>	0.00	0.00	*400.00 F
14	1		*FRONT FENDER RH <i>bt</i>	0.00	0.00	*450.00 F
15	1		*FRONT FENDER COWLING RH <i>bt</i>	0.00	0.00	*55.00 F
16	10		*FRONT FENDER COWLING CLIPS <i>bt</i>	0.00	0.00	*20.00 F
17	1		*FRONT FENDER LAMP STICKER <i>bt</i>	0	0.00	<i>30</i> *50.00 FS
18	1		*FRONT SPORT RIM RH <i>bt</i>	0	0.00	<i>350</i> *300.00 FS
19	1		*FRONT KNUCKLE HUB BEARING RH <i>?</i>	0.00	0.00	*205.00 F
20	1		*FRONT KNUCKLE ARM RH <i>?</i>	0.00	0.00	*240.00 F
21	1		*FRONT LOWER ARM RH <i>bt</i>	0.00	0.00	*165.00 F

F=Franchise part, S=SpclNett.

Sub Total (\$\$)	4,028.00
+ Margin on L,N Items 10.00% (\$\$)	344.80
Total Parts (\$\$)	4,372.80

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Labour

Particulars	Lab.Type	Amount
Labour Items		
1 TO KNOCK & STRAIGHTEN FRONT BODY MEMBER, ASSEMBLY & REPAIR ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	600 800.00
2 SPRAY PAINT BONNET, FRONT BUMPER, FRONT FENDER, FRONT FENDER INNER PANEL RH	New	700 800.00
3 REMOVE & REPLACE A/C CONDENSER, PIPE, NOSE & FLOOD LIGHT ASSEMBLY	New	X 120.00
4 REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION	New	80 150.00
5 COMPUTER WHEEL ALIGNMENT	New	60.00
6 RUST PROOF AFFECTED AREAS	New	30.00
Gross Labour Cost (\$\$)		1,960.00

Report was unsuited during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Panel
Hp 90010068
6 days
L/S
08/03/23 @ 1430
Rey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 106A

Vehicle Details

Vehicle No.: SLZ4321T

Vehicle to be Exported: No

Intended Deregistration Date: 09 Mar 2023

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA AD 1.6 GLS AT (AMS)

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: G4FGJU188498

Chassis No.: KMHD841CMJU688035

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$10,057.00

Original Registration Date: 03 May 2018

First Registration Date: 03 May 2018

Transfer Count: 0

Actual ARF Paid: \$10,057.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 May 2028

PARF Rebate Amount: \$7,542.00

Intended COE Rebate Details

COE Expiry Date: 02 May 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$38,510.00

COE Rebate Amount: \$19,821.00

Total Rebate Amount: \$27,363.00

Hyundai Elantra 1.6A GLS

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)**Price****\$71,800****Depreciation** ⓘ

\$12,710 /yr

[View models with similar depre](#)**Reg Date**

19-Apr-2018

(5yrs 1mth 9days COE left)

Mileage

71,350 km (14.6k /yr)

Manufactured ⓘ

2018

Road Tax ⓘ

\$738 /yr

Transmission

Auto

Dereg Value ⓘ

\$29,069 as of today (change)

OMV ⓘ

\$13,524

COE ⓘ

\$37,000

ARF ⓘ

\$13,524

Engine Cap

1,591 cc

Power

93.8 kW (125 bhp)

Curb Weight ⓘ

1,345 kg

No. of Owners ⓘ

3

Type of Vehicle

Mid-Sized Sedan