



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 1

Vehicle No. SJP2597D

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>Distorted</i>		688.40	✓
2	FRONT BUMPER SIDE HOLDER @35.20 <i>Dmg</i>		70.40	✓
3	FRONT BUMPER REINFORCEMENT <i>Distorted</i>		296.70	✓
4	FRONT BUMPER LOWER GRILLE <i>Dmg</i>		145.40	✓
5	FRONT BUMPER FOG LAMP COVER @65.20 <i>MP</i>		130.40	+
6	FRONT GRILLE <i>Smashed</i>		259.40	✓
7	FRONT GRILLE CHROME MOULDING <i>Missing</i>		230.30	✓
8	FRONT GRILLE LOGO <i>Missing</i>		48.90	✓
9	HEADLAMP @680.70 <i>Crash</i>		1361.40	✓
10	HEADLAMP LOWER BRACKET @45.90 <i>Crash</i>		91.80	✓
11	BONNET <i>Distorted</i>		761.90	✓
12	BONNET LOCK <i>Dmg</i>		98.10	✓
13	BONNET HINGE @55.20 <i>Bent</i>		110.40	✓
14	BONNET INSULATOR <i>Crushed</i>		162.40	✓
15	FRONT SUPPORT PANEL <i>Distorted</i>		566.50	✓
16	FRONT SUPPORT PANLE TOP COVER <i>Crashed</i>		167.40	✓
17	FRONT FENDER @576.40 <i>Dented</i>		1152.80	✓
18	HORN @76.2 <i>7 piece dmd</i>		152.40	76.20
19	AIR CON CONDENSER <i>Distorted</i>		1086.40	✓
20	AIR CON FAN COWLING ?		129.60	?
21	AIR CON FAN BLADE ?		65.20	?
22	AIR CON FAN MOTOR ?		356.40	?
23	AIR CON SUCTION PIPE ?		256.20	?
24	AIR CON DISCHARGE PIPE ?		289.50	?
25	AIR CON LIQUID PIPE ?		214.90	?
26	RADIATOR <i>Distorted</i>		1284.40	✓
27	RADIATOR FAN COWLING ?		139.20	?
28	RADIATOR FAN BLADE ?		66.10	?
29	RADIATOR FAN MOTOR ?		341.90	?
30	RADIATOR SPARE TANK <i>Not new</i>		94.70	+
31	RADIATOR TOP HOSE <i>Twisted</i>		56.80	✓
32	STEERING AIR BAG	} Activated	1880.10	✓
33	STEERING AIR BAG SENSOR		379.60	✓
34	STEERING AIR BAG CLOCK SPRING		249.70	✓
35	DASHBOARD <i>torn</i>		1134.10	✓
36	DASHBOARD AIR BAG	} Activated	2587.40	✓
37	DASHBOARD AIR BAG SENSOR		379.60	✓
38	FRONT DRIVER SEAT BAG		696.90	✓
39	FRONT PASSENGER SEAT BELT		696.90	✓
40	AIR BAG ECU		834.30	✓
41	REAR NUMBER PLATE LAMP @62.20 <i>Not new</i>		124.40	+
42	REAR BUMPER <i>Distorted</i>		668.40	✓
43	REAR BUMPER SIDE HOLDER @34.10 <i>Damaged</i>		68.20	✓
44	REAR BUMPER TOW COVER <i>Distorted</i>		39.40	✓
45	REAR END PANEL <i>Distorted</i>		459.10	✓

46 REAR END PANEL INNER MEMBER } Distorted
 47 REAR END PANEL TOP GARNISH }
 48 TAILLAMP @366.50 LH and, RH ?
 49 TAILLAMP PANEL @390.10 LH Distorted
 50 TAILGATE Distorted
 51 TAILGATE LOCK Jammed
 52 TAILGATE WEATHERSTRIPE at
 53 TAILGATE DAMPER @212.10 ?
 54 TAILGATE INNER TRIM BOARD Delnd.
 55 TAILGATE OUTER GARNISH Auled
 56 TAILGATE WIPER MOTOR } Distorted
 57 TAILGATE WIPER ARM }
 58 TAILGATE INNER SIDE GARNISH @172.40
 59 TAILGATE GLASS Shattered
 60 TAILGATE GLASS MOULDING na
 61 HONDA LOGO }
 62 STREAM WORDING }
 63 FLOOR PANEL ?
 64 FLOOR PANEL TOP COVER @242.10 ?
 65 REAR FENDER @928.70 LH Buckled
 66 REAR FENDER INNER TRIM BOARD @295.40 ?
 67 REAR FENDER INNER SHIELD @80.10 ?
 68 REAR EXHAUST PIPE }
 69 REAR EXHAUST PIPE MOUNTING }
 70 REAR EXHAUST PIPE GASKET }
 71 REAR EXHAUST HEAT SHIELD }
 na
 na

186.90 ✓
 216.70 ✓
 733.00 ?
 780.20 380.10
 903.40 ✓
 189.40 ✓
 195.90 ✓
 424.20 ?
 285.10 ✓
 239.80 ✓
 361.90 ✓
 70.20 ✓
 344.80 ?
 1280.20 ✓
 124.10 ✓
 45.90 ✓
 49.10 ✓
 1062.70 ?
 482.20 ?
 1857.40 928.70
 590.80 ?
 160.20 ?
 678.10 x
 35.80 x
 32.60 x
 115.90 x

less	20%	32520.90	20%	
		6504.18		
		26016.72		

SPECIAL NETT ITEMS

1 FRONT NUMBER PLATE } Distorted
 2 FRONT NUMBER PLATE HOLDER }
 3 FRONT BUMPER CLIPS }
 4 FRONT GRILLE CLIPS }
 5 BONNET INSULATOR CLIPS na
 6 FRONT SUPPORT PANEL TOP COVER CLIPS na
 7 COOLANT na
 8 REAR NUMBER PLATE }
 9 REAR NUMBER PLATE HOLDER }
 10 REAR BUMPER CLIPS na
 11 REVERSE SENSOR }
 12 REAR END PANEL TOP GARNISH CLIPS na
 13 REAR END PANEL SEALANT na
 14 TAILGATE INNER TRIM BOARD CLIPS na
 15 TAILGATE OUTER GARNISH CLIPS na
 16 TAILGATE INNER SIDE GARNISH CLIPS na
 17 TAILGATE GLASS SEALANT }
 18 TAILGATE GLASS SOLAR FILM }
 19 FLOOR PANEL INSULATION PADS ?
 20 REAR FENDER INNER TRIM CLIPS na
 21 REAR FENDER INNER SHIELD CLIPS na
 22 REAR FENDER GLASS SEALANT na

30.00 ✓
 30.00 ✓
 50.00 30
 20.00 ✓
 50.00 30
 20.00 ✓
 50.00 ✓
 30.00 ✓
 30.00 ✓
 50.00 ✓
 50.00 ✓
 280.00 200
 20.00 ✓
 60.00 ✓
 30.00 ✓
 30.00 ✓
 50.00 ✓
 60.00 ✓
 300.00 200
 280.00 ?
 60.00 ✓
 30.00 x
 100.00 40

Total Parts

1660.00

**AUTO UNITED SG PTE LTD**

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 2

Vehicle No. SJP2597D

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	4000.00	2800
2	SPRAY PAINTING	3400.00	2300
3	WIRING	200.00	60
4	TO APPLY TUFF COAT	250.00	180
5	TO REMOVE UPHOLSTERY	150.00	80
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00	60
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00	60
8	TO REMOVE DRIVER & PASSENGER AIR BAGS	500.00	350
9	TO REMOVE DRIVER & PASSENGER SEAT BELTS	250.00	100
10	TO RESET AIR BAG SYSTEM	380.00	280
11	TO REMOVE UPHOLSTERY	150.00	X
12	TO TRANSFER TAILGATE FITTINGS	150.00	80
13	TO REMOVE TAILGATE GLASS	180.00	120
14	TO REMOVE REVERSE SENSOR	100.00	50
15	TO VACCUUM GLASS SHARDS & TO STEAM CLEAN INTERIOR	150.00	80
16	TO REMOVE FUEL TANK	150.00	60
17	TO REMOVE FENDER GLASSES	240.00	50
18	TO REMOVE REAR EXHAUST PIPE	150.00	+
	Labour Total :	10640.00	
	TOTAL (PARTS & LABOUR):	383167.20	

Adrian Cj
H/s. 09/02/23.
21 Days.