



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29.

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 1

Vehicle No. SJP2597D

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>Distorted</i>		688.40	✓
2	FRONT BUMPER SIDE HOLDER @35.20 <i>Dist</i>		70.40	✓
3	FRONT BUMPER REINFORCEMENT <i>Distorted</i>		296.70	✓
4	FRONT BUMPER LOWER GRILLE <i>Dist</i>		145.40	✓
5	FRONT BUMPER FOG LAMP COVER @65.20 <i>no m</i>		130.40	+
6	FRONT GRILLE <i>Smashed</i>		259.40	✓
7	FRONT GRILLE CHROME MOULDING <i>Missing</i>		230.30	✓
8	FRONT GRILLE LOGO <i>Missing</i>		48.90	✓
9	HEADLAMP @680.70 <i>Crashed</i>		1361.40	✓
10	HEADLAMP LOWER BRACKET @45.90 <i>Crashed</i>		91.80	✓
11	BONNET <i>Distorted</i>		761.90	✓
12	BONNET LOCK <i>Dist</i>		98.10	✓
13	BONNET HINGE @55.20 <i>Bent</i>		110.40	✓
14	BONNET INSULATOR <i>Crumpled</i>		162.40	✓
15	FRONT SUPPORT PANEL <i>Distorted</i>		566.50	✓
16	FRONT SUPPORT PANLE TOP COVER <i>Distorted</i>		167.40	✓
17	FRONT FENDER @576.40 <i>Dented</i>		1152.80	✓
18	HORN @76.2 <i>7 piece dented</i>		152.40	7-76.20
19	AIR CON CONDENSER <i>Distorted</i>		1086.40	✓
20	AIR CON FAN COWLING <i>3 new</i>		129.60	7
21	AIR CON FAN BLADE <i>3 new</i>		65.20	7
22	AIR CON FAN MOTOR <i>3 new</i>		356.40	7
23	AIR CON SUCTION PIPE <i>3 new</i>		256.20	7
24	AIR CON DISCHARGE PIPE <i>3 new</i>		289.50	7
25	AIR CON LIQUID PIPE <i>3 new</i>		214.90	7
26	RADIATOR <i>Distorted</i>		1284.40	✓
27	RADIATOR FAN COWLING <i>3 new</i>		139.20	7
28	RADIATOR FAN BLADE <i>3 new</i>		66.10	7
29	RADIATOR FAN MOTOR <i>3 new</i>		341.90	7
30	RADIATOR SPARE TANK <i>3 new</i>		94.70	+
31	RADIATOR TOP HOSE <i>Twisted</i>		56.80	✓
32	STEERING AIR BAG <i>Activated</i>		1880.10	✓
33	STEERING AIR BAG SENSOR <i>Activated</i>		379.60	✓
34	STEERING AIR BAG CLOCK SPRING <i>Activated</i>		249.70	✓
35	DASHBOARD <i>torn</i>		1134.10	✓
36	DASHBOARD AIR BAG <i>Activated</i>		2587.40	✓
37	DASHBOARD AIR BAG SENSOR <i>Activated</i>		379.60	✓
38	FRONT DRIVER SEAT <i>Belt</i>		696.90	✓
39	FRONT PASSENGER SEAT BELT <i>Activated</i>		696.90	✓
40	AIR BAG ECU <i>Activated</i>		834.30	✓
41	REAR NUMBER PLATE LAMP @62.20 <i>3 new</i>		124.40	+
42	REAR BUMPER <i>Distorted</i>		668.40	✓
43	REAR BUMPER SIDE HOLDER @34.10 <i>Damaged</i>		68.20	✓
44	REAR BUMPER TOW COVER <i>Distorted</i>		39.40	✓
45	REAR END PANEL <i>Distorted</i>		459.10	✓

46	REAR END PANEL INNER MEMBER		186.90	/
47	REAR END PANEL TOP GARNISH	Distorted	216.70	/
48	TAILLAMP @366.50	LH Cured, RH New	733.00	7 366.50
49	TAILLAMP PANEL @390.10	LH Distorted	780.20	390.10
50	TAILGATE	Distorted	903.40	/
51	TAILGATE LOCK	Jammed	189.40	/
52	TAILGATE WEATHERSTRIPE	OK	195.90	/
53	TAILGATE DAMPER @212.10	New	424.20	✗
54	TAILGATE INNER TRIM BOARD	Del'd	285.10	/
55	TAILGATE OUTER GARNISH	Cured	239.80	/
56	TAILGATE WIPER MOTOR	Distorted	361.90	/
57	TAILGATE WIPER ARM		70.20	/
58	TAILGATE INNER SIDE GARNISH @172.40	New	344.80	✗
59	TAILGATE GLASS	Shattered	1280.20	/
60	TAILGATE GLASS MOULDING	New	124.10	/
61	HONDA LOGO	New	45.90	/
62	STREAM WORDING		49.10	/
63	FLOOR PANEL	Distorted	1062.70	/
64	FLOOR PANEL TOP COVER @242.10	Del'd	482.20	/
65	REAR FENDER @928.70	LH Buckled	1857.40	928.70
66	REAR FENDER INNER TRIM BOARD @295.40	Del'd LH	590.80	295.40
67	REAR FENDER INNER SHIELD @80.10	New	160.20	✗
68	REAR EXHAUST PIPE		678.10	✗
69	REAR EXHAUST PIPE MOUNTING		35.80	✗
70	REAR EXHAUST PIPE GASKET		32.60	✗
71	REAR EXHAUST HEAT SHIELD		115.90	✗
			26463.90	
			21171.12	
			less	
			20%	
			20%	
			26016.72	
			32520.90	
			6504.18	
			26016.72	
			30.00	/
			30.00	/
			50.00	30
			20.00	/
			50.00	30
			20.00	/
			50.00	/
			30.00	/
			30.00	/
			50.00	/
			280.00	200
			20.00	/
			60.00	/
			30.00	/
			30.00	/
			50.00	/
			60.00	/
			300.00	200
			280.00	200
			60.00	/
			30.00	/
			100.00	40
			1660.00	
			Total Parts	

SPECIAL NETT ITEMS

- FRONT NUMBER PLATE Distorted
- FRONT NUMBER PLATE HOLDER
- FRONT BUMPER CLIPS New
- FRONT GRILLE CLIPS New
- BONNET INSULATOR CLIPS New
- FRONT SUPPORT PANEL TOP COVER CLIPS New
- COOLANT New
- REAR NUMBER PLATE Distorted
- REAR NUMBER PLATE HOLDER
- REAR BUMPER CLIPS New
- REVERSE SENSOR Distorted
- REAR END PANEL TOP GARNISH CLIPS New
- REAR END PANEL SEALANT New
- TAILGATE INNER TRIM BOARD CLIPS New
- TAILGATE OUTER GARNISH CLIPS New
- TAILGATE INNER SIDE GARNISH CLIPS New
- TAILGATE GLASS SEALANT New
- TAILGATE GLASS SOLAR FILM New
- FLOOR PANEL INSULATION PADS New
- REAR FENDER INNER TRIM CLIPS New
- REAR FENDER INNER SHIELD CLIPS New
- REAR FENDER GLASS SEALANT New



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 2

Vehicle No. SJP2597D

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	PANEL BEATING	4000.00	2800
2	SPRAY PAINTING	3400.00	2300
3	WIRING	200.00	60
4	TO APPLY TUFF COAT	250.00	180
5	TO REMOVE UPHOLSTERY	150.00	80
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00	60
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00	60
8	TO REMOVE DRIVER & PASSENGER AIR BAGS	500.00	350
9	TO REMOVE DRIVER & PASSENGER SEAT BELTS	250.00	100
10	TO RESET AIR BAG SYSTEM	380.00	280
11	TO REMOVE UPHOLSTERY	150.00	X
12	TO TRANSFER TAILGATE FITTINGS	150.00	80
13	TO REMOVE TAILGATE GLASS	180.00	120
14	TO REMOVE REVERSE SENSOR	100.00	50
15	TO VACCUUM GLASS SHARDS & TO STEAM CLEAN INTERIOR	150.00	80
16	TO REMOVE FUEL TANK	150.00	60
17	TO REMOVE FENDER GLASSES	240.00	50
18	TO REMOVE REAR EXHAUST PIPE	150.00	+
	Labour Total :	10640.00	
	TOTAL (PARTS & LABOUR):	383167.20	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G

H/s. 09/02/23.

21 Days.

Total: 29101.12

C/S 12.3K.
(Nett Value).