


REC BY: T. J. M. REF: C2/A162300/365/Tips

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To Inspco/Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$215K
IDAC Accident Report Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SNF242X Yr Regn: 2022 April
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Audi A5 C.C. 1984
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 8473 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WAUZZZF5XNA002289
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modl: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 245/40R18
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO, or Hankook
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 10/2/23
Survey held at Premium ubi.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction

Date/Time, File Pass 40? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Rep. Format: _____
Lamp Comp / L.B. k / p

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____
Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0163/2023/EQ
DATE : 9-Feb-23
WIP : 62469

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023
YOUR INSURED VEH NO : SJT 679 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : M/S MITSUBISHI HC CAPITAL ASIA PACIFIC PTE. LTD.
ADDRESS : 111 SOMERSET ROAD
#14-05 TRIPLEONE SOMERSET
SINGAPORE 238164
TELEPHONE : HP +65 96396494
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : **SNF 242 X**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 26/4/2022
ENGINE NO : DEM 034491
CHASSIS NO : WAUZZZF5XNA002289
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Feb-23
PLACE OF ACCIDENT : JUNCTION OF AIRPORT ROAD AND UBI AVE 2 BEFORE BARTLEY
KPE ENTRANCE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 242 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION.	S/N \$	360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00 500	
3	TO RESPRAY REAR BUMPER.	\$	1,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 242 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,763.00	de ✓
2	REAR BUMPER SECURING STRIP - UPPER	1	\$ 133.00	re ✓
3	REAR BUMPER SECURING STRIP - LOWER	1	\$ 264.00	re ✓
4	REAR BUMPER SPOILER	1	\$ 292.00	inf ✓
5	REAR BUMPER BRACKET - LH / RH	2	\$ 482.00	X
6	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 812.00	X
7	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	X
8	REAR PARKING AID SEAL RING	4	\$ 11.00	re ✓
9	REAR PARKING AID SEAL RING	2	\$ 9.00	X
10	REAR PARKING AID SEAL RING	2	\$ 6.00	re ✓
11	REAR PARKING AID SEAL RING	2	\$ 9.00	re ✓
12	REAR BUMPER WIRING SET	1	\$ 452.00	X
13	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,197.00	?
14	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00	?
15	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 54.00	?
16	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 200.00	?
17	SUNDRIES		\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 7,461.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 10,213.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanjil 97495249
WP, 10/2/23 @ 340
- 3 days
resurvey before part
Tanjil claimants can.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT