

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202332005142 Date: 06th Apr 2023

Our Ref: CS6/AIS23001365/Hvy3e2

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SMH 2079P ACCIDENT ON 03/02/2023

We thank you for your instruction on 09/02/2023.

The following vehicle information was recorded:

Registration Number : SMH 2079P

Make & Model : Toyota Harrier M Grade Chassis Number : JTEZB3GH50J003772

Year of Registration : 2019 Engine Capacity : 1998 cc

- 1. The vehicle sustained damages at the rear portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.