LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Sharon Lim 22 Feb 2023 Attn: Date:

Preliminary Advice

Vehicle No : SMH2079P Accident Date : 03/02/2023 Make : TOYOTA HARRIER Policy No. : SP2002093149-01 Assignment Date : 09/02/2023 **Excess** : S\$600.00

Date of Inspection : DESKTOP SURVEY Est. Duration of Repair :4

Inspection At : MOVA AUTOMOTIVE PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,569.70
Revised Amount	:S\$	3,931.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,931.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 108,000.00 COE / PARF Rebate :S\$ 44,621.00

Salvage Value :S\$

Margin for Repair :S\$ 63,379.00

Remarks

(X)	The vehicle is repairable at our	adjusted amount.	We have also	confirmed	excess and	d policy coverage	e. Kindly let
	us have your authorisation.						

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Lump Sum repair

> Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.