

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0037/2023
DATE : 06-FEB-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)
TEL : 63954779/67143369
FAX : 63953768
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR EDWIN JOSEPH WHEELER JR
ADDRESS : 35 MOUNT SINAI LANE

S(275788)
TELEPHONE NO : 97567680/97662420

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : SMF9963B
VEHICLE NO : SMF9963B
MODEL CODE : JDRNRRZT32EWF---A
MODEL/YEAR : NISSAN X-TRAIL FACELIFT MY2017
ENGINE NO : MR20385055C
CHASSIS NO : JN1JANT32Z0011658
MILEAGE : 1 KM
DATE IN : 06/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 03/02/2023

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF9963B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	✓
2 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR 3X AFFECTED PANEL	360.00 120	
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	✓
5 WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	? X AM
6 ZZ/001	REPAIR RH FR FENDER, UPP/LH/HOODLEDGE PANEL, A-PILLR LH FR DOOR & RENEW FR BUMPER & HOOD @340 x 4	2340.00 1560	✓
7 ZZ/002	S/PAINT RH/LH FR FENDER, LH FR DOOR/A.PILLR/HOODLGE FR PANEL ASSY, HOOD & FR BUMPER @250 x 6	1875.00 1500	✓
	TOTAL LABOUR CHARGES	5303.00	3668

11/18/16

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF9963B

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	CLIP TRIM(\$3.5X2) <i>ne</i>	76882-JG10A	7.00		
2	CLIP, TRIM(\$2.9X3) <i>m</i>	01553-10641	8.70		
3	MOULDING ASSY-F <i>de</i>	63861-4CE1A	194.50		
4	COVER-FR FDR, LH <i>scr</i>	66895-4CL0A	25.60		
5	HINGE RH <i>st</i>	65400-4CL0A	48.20		
6	ENERGY ABSORBER <i>X NN</i>	62090-6FR0A	352.70		
7	BRKT-BPR SIDE, R <i>X NN</i>	62222-4CL0A	47.80		
8	BRKT-BPR SIDE, L <i>ne</i>	62223-4CL0A	47.80		
9	CLIP(\$1.4X10) <i>m</i>	01553-10501	14.00		
10	BUMPER SET FR <i>de</i>	62022-6FS0H	641.60		
11	BRACE ASSY-R/CO <i>repair</i>	62511-4CE0A	240.20		
12	FENDER-FRONT LH <i>buc</i>	F3101-4CCMA	692.30		
13	FENDER-FRONT RH <i>buc</i>	F3100-4CCMA	692.30		
14	SUPPORT ASSY-RA <i>Repair</i>	62513-4CB0A	54.70		
15	HOOD <i>buc</i>	F510M-4CCMA	1075.30		
16	INSULATOR-HOOD <i>de</i>	65840-4CC1A	175.30		
17	CLIP-INSUL(\$1.9X11) <i>m</i>	65846-30F00	20.90		
18	HOOD HINGE ASSY <i>bt</i>	65401-4CL0A	48.20		
19	MALE ASSY-HOOD <i>X NN</i>	65601-4CE1C	74.50		
20	LAMP ASSY-LH <i>ca</i>	26060-6FP7B	2608.60		
21	DUCT, AIR FR <i>? X nn</i>	16554-4BB0A			117.20
22	DUCT ASSY-AIR <i>? X nn</i>	16554-4BB0D			61.80
23	SUNDRIES	NPN			30.00 <i>20</i>
SUB TOTAL			7070.20	0.00	209.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1414.04	0.00	0.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF9963B

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
GRAND TOTAL		✓ 5656.16	0.00	209.00
OVERALL TOTAL		5865.16		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF9963B

TOTAL LABOUR CHARGES	5303.00
TOTAL SPARE PARTS CHARGES	5865.16
GRAND TOTAL	11168.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 900100168
SURVEYED DATE	:	08/02/23 @ 1710
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 7 days
LIABILITY	:	0.00 p/p
REMARKS	:	

EXCESS: 400

Revert

Resury before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: