



Final Report

Estimate No. : **b1 64916**
Date Estimated : **06/02/2023**
Prepared By : **Han Kwan Yong**

Page No. :

- ESTIMATE REPAIR FOR -

Samuel Rotandi
103 Lorong Sarina
#01-08

Singapore 416730

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMV5581L	WBA5R12020AK72314	31/07/2019	330i LIM	47373

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, RH trim grille with PDC include carrying out necessary repairs caused by the accident	850.00		850.00
To respray front bumper	986.00		986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00		168.00
To check electrical wiring system at the front section for proper function	168.00		168.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH TRIM GRILLE WITH PDC (M/PDC)	88.65	1.00	0.00	88.65
FRT BUMPER PANEL PRIMED (M/PDC/PMA)	1,342.30	1.00	0.00	1,342.30

SUPPLEMENTARY ITEMS

Total Labour :	2,252.00
Total Parts :	1,430.95
Total Labour & Parts (before GST) :	3,682.95
Deduction for Excess :	
Total Repair Costs less Excess:	3,682.95
GST @8%:	294.64
Grand Total :	3,977.59

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

