

Your Ref : SNM23D200975/C01/TOHHS

Date: 15th Feb 2022

Our Ref : CS/CTI23001374/Twp3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMX 223T
ACCIDENT ON 19/01/2023**

Instruction was received to inspect the vehicle Reg. No. SMX 223T. The inspection was conducted on 09/02/2023 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd, Blk 3, Pioneer Road North, #01-18, Singapore 628457.

The following vehicle information was recorded:

Registration Number	: SMX 223T
Make/Model	: Toyota Alphard 2.4S A
Year of Registration	: 2008
Body Colour	: Burnt
Chassis Number	: ANH208019756
Engine Capacity	: 2362 cc

The vehicle caught fire. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 76,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 18,187.00
Nett Liability	<u>S\$ 57,813.00</u> =====

Vehicle Inspected By:



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.