



發 福 摩 哆 車 房

HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.

Tel / Fax: 6445 2934 Hp: 8161 6988

BUSINESS REG NO. 375854/00C

Not Actual
14/2/23
1/5 @ 1600/
3 days.
Cheng He Atkinson

Carplate: GBE5152L
Chassis No: JTFHT02P800187239
Accident Date: 07/02/2023
Make & Model: Toyota HiAce

No.	Item	Nett Price	<input checked="" type="checkbox"/> / <input type="checkbox"/>	Remarks
1	Front Bumper	\$ 595.10		cu ✓
2	Front Bumper Side Retainer (LH)	\$ 114.30		cu ✓
3	Front Bumper Reinforcement Beam	\$ 429.10		17 X
4	Headlamp LH	\$ 718.20		cu ✓
5	Front Door LH	\$ 1,406.10		2 X
6	Front Door Hinge LH (Upper)	\$ 74.10		17 X
7	Front Door Hinge LH (Lower)	\$ 74.10		17 X
8	Front Door Check LH	\$ 120.10		17 X
9	Front Door LH Step-up Garnish	\$ 115.10		good ✓
10	Front Door LH Step-Up Panel	\$ 435.00		2 X
11	Front Shock Absorber LH	\$ 325.90		17 X
12	Front Wheel Bearing LH	\$ 136.20		17 X
13	Front Wheel Hub LH	\$ 385.10		17 X
14	Front Lower Arm LH	\$ 149.20		17 X
15	Front Wheel Rim Cover LH	\$ 150.60		17 X
16	Front Door LH Trim Board	\$ 408.10		17 X
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

(252)

5636.30.

	Special Nett Items	Price	✓/✗	Remarks
1	Front Bumper Clips (1set)	\$ 40.00		Net ✓
2	Front Door Trim Board Clips (1set)	\$ 40.00		17 X
3	Front Tyre LH	\$ 290.00		49 X
4	Front Tyre Rim LH	\$ 380.00		17 X
5	Front Door LH Sticker	\$ 580.00		Net 300
6	Front Door LH Company Sticker	\$ 50.00		Net 30
7				
8				
9				
10				
11				
No.	All Necessary Work	Price	✓/✗	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		17 X
2	Under Carriage Works (Including Removal of Shock absorber, Spring, Lower Arm, Wheel Hub, Brake Assembly, Wheel Bearing and all necessary)	\$ 380.00		17 X
3	Transfer of Front Door Mechanism	\$ 120.00		17 X
4	To Remove and Re-stick Sticker	\$ 250.00		17 X
5	4 Wheel Alignment	\$ 180.00		17 X
6	Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts)	\$ 800.00		300
7	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 900.00		200
	Estimated No. of days for repairs and respray of all necessary	6 Days		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts pending resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9766-30

P-1542-7
 252
 1157.02
 370
 520
 2027.02
 20%
 1121