

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TP Allianz
Xiao Tony

MK TRANS

BLK 289 YISHUN AVE 6 #11-18

SINGAPORE 760289

TAX INVOICE

Repair Code : CLM15803

Date in : 07/02/2023

Vehicle Num. : SMC2132U

Model : TOYOTA VOXY HYBRID 1.8V A

Chassis/Eng# : ZWR800317419/2ZR0B46624

Contact : 91065802

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehnd</i>	1	972.50	972.50
REAR BUMPER SIDE RETAINER L/R <i>neu</i>	2	93.60	187.20
REAR BUMPER TOW HOOK COVER <i>neu</i>	1	36.30	36.30
REAR END PANEL <i>Dented</i>	1	752.70	752.70
REAR FLOOR PANEL TOP BOARD COVER <i>torn</i>	1	1175.40	1175.40 691
REAR LH TAILLAMP LOWER GARNISH <i>neu</i>	1	374.70	374.70
REAR LH TAILLAMP LOWER GARNISH BRACKET <i>neu</i>	1	180.70	180.70
REAR TAILGATE <i>Dented</i>	1	1753.60	1,753.60
REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM <i>neu</i>	1	65.00	65.00
REAR TAILGATE INNER PULL HANDLE GARNISH <i>neu</i>	1	190.10	190.10
REAR TAILGATE INNER TRIM BOARD <i>Dented</i>	1	605.10	605.10
REAR TAILGATE MECHANISM LOCK <i>Dy'd</i>	1	846.50	846.50 461
REAR TAILGATE NUMBER PLATE LAMP L/R <i>neu</i>	2	69.10	138.20
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>neu</i>	2	43.70	87.40
REAR TAILGATE WEATHER STRIP <i>Int</i>	1	372.30	372.30
REAR TAILGATE WINDSCREEN MOULDING L/R <i>neu</i>	2	50.90	101.80

*** This is a computer-generated document which requires no signature.***

page 1

Rear end panel top garnish
Rehnd

220.00

chrome plate
neu

280
SR 3000

5985

449625

S.N: 250

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MK TRANS
BLK 289 YISHUN AVE 6 #11-18
SINGAPORE 760289

Contact : 91065802

TAX INVOICE

Repair Code : CLM15803

Date in : 07/02/2023

Vehicle Num. : SMC2132U

Model : TOYOTA VOXY HYBRID 1.8V A

Chassis/Eng# : ZWR800317419/2ZR0B46624

Subtotal before discount		7,839.50
Percentage discount 25%		1,959.88
Sub-total 1		5,879.63
REAR BUMPER CHROME MOULDING <i>Nu</i>	1	400.00 <i>250. 400.00</i>
REAR BUMPER CLIPS - SET <i>Nu</i>	1	50.00 <i>30. 50.00</i>
REAR BUMPER REVERSE SENSOR - SET <i>Revised</i>	1	250.00 <i>200. 250.00</i>
REAR BUMPER SIDE WEATHER STRIP L/R <i>Nu</i>	2	100.00 <i>80. 200.00</i>
REAR TAILGATE INNER LOWER WEATHER STRIP <i>Nu</i>	1	100.00 <i>50. 100.00</i>
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Nu</i>	1	50.00 <i>30. 50.00</i>
Subtotal before discount		1,050.00
Percentage discount 0%		0.00
Sub-total 2		1,050.00
Parts-total		6,929.63

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

✓ 60.00
120 150.00
60 160.00
800 1,000.00
800 1,000.00
80 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MK TRANS
BLK 289 YISHUN AVE 6 #11-18
SINGAPORE 760289

Contact : 91065802

TAX INVOICE

Repair Code : CLM15803

Date in : 07/02/2023

Vehicle Num. : SMC2132U

Model : TOYOTA VOXY HYBRID 1.8V A

Chassis/Eng# : ZWR800317419/2ZR0B46624

To remove, reinstall tailgate mechanism and check for function

1960

Labour Total

2,530.00

Parts & Labour Total

9,459.63

60 80.00

*** This is a computer-generated document which requires no signature.***

page 3

Adrian
2/s 09/02/23
06 P.m.

Total : 7346.25
2/s : 5.8K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: