



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2301615

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 16/03/2023
Reference CS3/III23001409/Sqy3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SJW 8012Z
Insured Veh. SHD 2605B
Claim No. MFL2023D0001721
Policy No. D20MFL0006372_02
Accident Date 04/02/2023
Inspection Date 10/02/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 10.02.2023 03.00pm	
- Dismantle Inspection 13.02.2023 04.00pm	
- After Repair Inspection 16.02.2023 02.40pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM