

24	HONDA LOGO <i>new</i>	1	\$ 30.40	\$ 30.40	+
25	VE ZEL EMBLEM <i>new</i>	1	\$ 45.90	\$ 45.90	+
26	SPARE TYRE PANEL <i>Rejis</i>	1	\$ 1,130.00	\$ 1,130.00	+
27	SPARE TYRE PANEL TOP COVER <i>delud</i>	1	\$ 306.60	\$ 306.60	+
28	SPARE TYRE PANEL TOOLS TRAY SPONGE <i>new</i>	1	\$ 285.40	\$ 285.40	+
29	SPARE TYRE PANEL UNDERCOVER <i>new</i>	1	\$ 225.10	\$ 225.10	+
30	REAR FENDER ARC GARNISH <i>3AP</i>	2	\$ 196.00	\$ 392.00	+
31	REAR FENDER INNER SHIELD <i>3AP</i>	2	\$ 147.50	\$ 295.00	+
32	REAR FENDER INNER TRIM BOARD <i>RH outd</i>	2	\$ 305.20	\$ 610.40	+

Hybrid Emblem. 58. ✓
New
4943.50
3954.80

TOTAL PRICE: \$ 10,621.50
LESS 20% \$ 2,124.30
SUB TOTAL PRICE: \$ 8,497.20

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 30.00	\$ 30.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
3	REVERSE SENSOR (SET) <i>delud</i>	1	\$ 280.00	\$ 280.00	2w
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	10.
5	TAILGATE OUTER GARNISH CLIPS (SET) <i>new</i>	1	\$ 25.00	\$ 25.00	+
6	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
7	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00	+
8	SPARE TYRE PANEL UNDERCOVER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
9	SPARE TYRE PANEL INSULATION PAD <i>new</i>	1	\$ 250.00	\$ 250.00	+
10	REAR FENDER ARC GARNISH CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00	+
11	REAR FENDER INNER SHIELD CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00	+
12	REAR FENDER INNER TRIM BOARD CLIPS (SET) <i>new</i>	2	\$ 30.00	\$ 60.00	+
13	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00	+
TOTAL :				\$ 1,415.00	

360

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	<i>850</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>800</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
5	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
6	TO REMOVE VIDEO RECORDER	\$ 100.00	<i>50</i>	
7	TO REMOVE UPHOLSTERY AND REAR SEAT	\$ 380.00	<i>80</i>	
8	TO SPRAY TUFF COAT	\$ 150.00	<i>80</i>	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>80</i>	
10	TO REPLACE TAILGATE GLASS	\$ 180.00	<i>120</i>	
TOTAL		\$ 4,260.00		

2190

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,912.20
TOTAL LABOUR COST: \$ 4,260.00
TOTAL REPAIR COST: \$ 14,172.20

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

FAX:

Total: 6504.80

h/s: 5.2K

06 Days

5.2K
06 days

LKK

LKK Auto Consultants Pte Ltd
240 Hill Street, Singapore 059511
Tel: 6733 1111 Fax: 6733 1112

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: