

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 533734628

DATE : 01.02.2023

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
VEHICLE NO : **SML233C**
MODEL : **TOYOTA HARRIER**
CHASSIS : **JTEAD3BH20J000598**
DATE OF ACCIDENT : 02.01.2023
DATE OF REG : 21.07.2021

Xiao Tony

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER LH	1	\$ 1,089.60	\$ 1,089.60
2	FRONT FENDER HYBRID EMBLEM LH	1	\$ 98.60	\$ 98.60
3	FRONT FENDER LOWER GARNISH LH	1	\$ 125.30	\$ 125.30
4	FRONT FENDER COWLING	1	\$ 298.60	\$ 298.60
5	FRONT DOOR LH	1	\$ 1,645.10	\$ 1,645.10
6	FRONT DOOR GARNISH LH	1	\$ 425.90	\$ 425.90
7	SIDE SKIRT LH	1	\$ 805.60	\$ 805.60
8	ABS SENSOR	1	\$ 325.60	\$ 325.60
9	FRONT RIM LH	1	\$ 1,198.60	\$ 1,198.60
10	FRONT KNUCLE ARM LH	1	\$ 587.70	\$ 587.70
11	FRONT WHEEL HUP C/W BEARING LH	1	\$ 598.60	\$ 598.60
12	FRONT SHOCK ABSORBER LH	1	\$ 498.60	\$ 498.60
13	FRONT LOWER ARM LH	1	\$ 679.20	\$ 679.20
14	FRONT STEERING RACK AND PINION	1	\$ 4,589.60	\$ 4,589.60
15	FRONT DRIVESHAFT LH	1	\$ 1,257.60	\$ 1,257.60
16	FRONT LINKAGE LH	1	\$ 146.70	\$ 146.70
17	FRONT BUMPER	1	\$ 987.60	\$ 987.60
18	FRONT BUMPER RETAINER LH	1	\$ 98.60	\$ 98.70

TOTAL PRICE \$ 14,370.90
LESS 25% \$ 3,592.73
SUB TOTAL PRICE \$ 10,778.18

1198.60
898.55

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
2	FRONT FENDER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
3	SIDE SKIRT LH CLIP	1	\$ 30.00	\$ 30.00
4	FRONT WHEEL TYRE LH	1	\$ 280.00	\$ 280.00

TOTAL \$ 410.00

220

220

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	200
3	TUFF COAT	\$ 250.00	x
4	WIRING CHECK	\$ 250.00	x 30
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	x
6	TO PRESS FRONT WHEEL BEARING	\$ 80.00	x
7	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	x
8	FOUR WHEEL ALIGNMENT	\$ 120.00	80
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL
\$ 5,080.00
ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,188.18
 TOTAL LABOUR COST : \$ 5,080.00
 TOTAL REPAIR COST : \$ 16,268.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

1/s 02/02/23.

02 sups

total: 1628.55

c/s: 1.3K ✓

510