

ASS. REC. BY:

REF:

HUA/ 23 001 4421K9

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1. B. / %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SND 1817S

Yr Regn:

12, 21

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai, Zonig

C.C.

1580

Colour

M. L. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

8116P

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM HC 8510VMU 262902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F: Wanli

195/65R15

R: Mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

8/2/23

D.O.I.

10/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 177

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S - RS, SI

) P. 100

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SND1817S*Not Authored
Penny B&P*

LAD2302-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

10 FEB 2023**SND1817S**

KMHC851CVMU262902

201603575K

HYUNDAI

IONIQ HYBRID

08/02/2023

SLX6965H / HL Assurance.

13/12/2021

PART

- 1 COVER - FRONT BUMPER
- 1 COVER - RADIATOR GRILLE UPPER
- 1 ABSORBER - FRONT BUMPER ENERGY
- 1 MOULDING - FRONT BUMPER CENTER, UPPER
- 1 BRACKET - FRONT BUMPER SIDE, LH
- 1 LAMP ASSY - HEAD, LH
- 1 LAMP ASSY-DAY RUNNING LIGHT, LH
- 1 MOULDING - FRONT BUMPER, LH
- 1 GRILLE ASSY - RADIATOR
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 HUB CAP

LIST

\$	Bul/cm	452.40	✓
\$	pu	48.30	X
\$		86.90	?
\$	nu	297.10	✓
\$	nu	28.00	✓
\$	mg/cm	2,110.30	✓
\$		642.50	?
\$	na/na	93.00	✓
\$	pu	460.20	X
\$	By	588.80	✓
\$	pu	114.70	X
\$	nu	235.60	✓

TOTAL \$ 5,157.80**25% \$ 1,289.45****\$ 3,868.35****Special Nett**

- 1 FENDER CLIP
- 1 FENDER LINER CLIP
- 1 RADIATOR GRILLE CLIP
- 1 FRT LH BUMPER SIDE CLIP
- 1 FRT RH BUMPER SIDE CLIP
- 1 FRT BUMPER CLIP
- 1 TYRE

TOTAL

\$	na	130.00	X
\$	na	65.00	✓
\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	✓
\$	pu	350.00	X
\$		805.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SND1817S

LAD2302-

TOTAL PARTS \$ 4,673.35**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 400

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 440

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 30

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 60

To Check Electrical Lighting Concerned.

\$ 170.00 20

TOTAL \$ 3,980.00**Over All Total** \$ 8,653.35**(PART-BY-PART) Repair Days**~~06 days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: