



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/022023/5974
Policy No:	SP2003011719-01	Date of Loss:	21/01/2023
Vehicle Reg. No.:	SMF1714G	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	WANG BIAODONG	Contact No:	+6598526601
Driver:	WANG BIAODONG		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	30/10/2018
Vehicle Colour:	White	Chassis No:	JTEZB3GH80J003376
Engine No:	8ARZ141711		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	16,373.00
Miscellaneous Items	0.00
Labour	1,690.00
Paintwork Labour	980.00
Towing	0.00
Gross Total (S\$)	19,043.00
+ GST 8.00% (S\$)	1,523.44
Nett Amount (S\$)	20,566.44

This claim is handled by: MUHAMMAD ISWAN BIN ISHAK

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2023)
 Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Vin's Motor Pte Ltd/SMF1714G/09/02/2023 15:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET CHROME MOULDING	0.00	0.00	*250.00 F	CRA
2	1		*RH HEADLAMP	0.00	0.00	*3,100.00 F	CRA
3	1		*LH HEADLAMP	0.00	0.00	*3,100.00 F	CRA
4	1		*RH HEADLAMP SPONGE (WHITE)	0.00	0.00	*40.00 F	CRA
5	1		*LH HEADLAMP SPONGE (WHITE)	0.00	0.00	*40.00 F	CRA
6	1		*RH HEADLAMP LOWER BRACKET	0.00	0.00	*50.00 F	CRA
7	1		*LH HEADLAMP LOWER BRACKET	0.00	0.00	*50.00 F	CRA
8	1		*FRONT GRILLE	0.00	0.00	*620.00 F	CRA
9	1		*FRONT GRILLE RH BRACKET	0.00	0.00	*60.00 F	CRA
10	1		*FRONT GRILLE LH BRACKET	0.00	0.00	*60.00 F	CRA
11	1		*FRONT GRILLE EMBLEM	0.00	0.00	*580.00 F	CRA
12	1		*FRONT RADAR WITH BRACKET	0.00	0.00	*950.00 F	CRA
13	1		*FRONT BUMPER	0.00	0.00	*1,100.00 F	CRA
14	1		*FRONT BUMPER CENTER LOWER GRILLE	0.00	0.00	*200.00 F	CRA
15	1		*FRONT BUMPER CENTER LOWER GARNISH	0.00	0.00	*280.00 F	CRA
16	1		*FRONT BUMPER RH FOG LAMP	0.00	0.00	*170.00 F	CRA
17	1		*FRONT BUMPER LH FOG LAMP	0.00	0.00	*170.00 F	CRA
18	1		*FRONT BUMPER RH FOG LAMP BRACKET	0.00	0.00	*90.00 F	CRA
19	1		*FRONT BUMPER LH FOG LAMP BRACKET	0.00	0.00	*90.00 F	CRA
20	1		*FRONT BUMPER LOWER PAD	0.00	0.00	*250.00 F	CRA
21	1		*FRONT BUMPER RH SIDE RETAINER	0.00	0.00	*60.00 F	CRA
22	1		*FRONT BUMPER LH SIDE RETAINER	0.00	0.00	*60.00 F	CRA
23	1		*FRONT BUMPER TOP BEAM	0.00	0.00	*150.00 F	CRA
24	1		*FRONT BUMPER SPONGE	0.00	0.00	*60.00 F	CRA
25	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*280.00 F	CRA
26	10		*FRONT BUMPER CLIPS	0.00	0.00	*20.00 F	CRA
27	1		*FRONT SUPPORT PANEL	0.00	0.00	*570.00 F	CRA
28	1		*BRACE PANEL	0.00	0.00	*260.00 F	CRA
29	1		*AIRCON CONDENSER	0.00	0.00	*1,100.00 F	CRA
30	1		*INTER COOLER	0.00	0.00	*420.00 F	CRA
31	1		*RADIATOR TOP RH SIDE GUIDE	0.00	0.00	*50.00 F	CRA
32	1		*RADIATOR TOP LH SIDE GUIDE	0.00	0.00	*50.00 F	CRA
33	1		*RADIATOR LOWER RH SIDE GUIDE	0.00	0.00	*50.00 F	CRA
34	1		*RADIATOR LOWER LH SIDE GUIDE	0.00	0.00	*50.00 F	CRA
35	1		*FRONT NO. PLATE	0	0.00	*40.00 FS	CRA
36	1		*FRONT BUMPER PARKING SENSOR	0	0.00	*380.00 FS	CRA
37	1		*COOLANT	0	0.00	*80.00 FS	CRA

F=Franchise part. S=SpcNett.

Sub Total (S\$) 14,930.00
 + Margin on L,N Items 10.00% (S\$) 1,443.00
 Total Parts (S\$) 16,373.00

Vin's Motor Pte Ltd/SMF1714G/09/02/2023 15:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO SPRAY PAINTING	New	980.00 ⁵⁰⁰
Labour Items			
2	TO REFILL AIRCON GAS	New	150.00 ^{X NN}
3	TO RESET HEADLAMP SYSTEM	New	280.00 ⁵⁰
4	TO RESET RADAR SYSTEM	New	380.00 ^{X NN}
5	TO REPAIR DAMAGES	New	880.00 ⁶⁰⁰
Gross Labour Cost (S\$)			2,670.00

Vin's Motor Pte Ltd/SMF1714G/09/02/2023 15:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NOT AUTHORISE.

DESKTOP SURVEY BY: EDWARD LIM (62563561)
20 FEB 2023

EXCESS TO BE ADVISED

P/A OR ~~HS~~ REPAIR?

5 DAYS FOR REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: