



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23001447/Uqy3e2	
			Date: 22/02/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6278K	Veh. Inspected	GBG 2077E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/02/23/2019	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	10/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KDH2015024874	Colour	SILVER
	Odometer	118123 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/02/2023	Inspection Date	10/02/2023
	Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	