

(08/11/13) wef

A&amp;S. REC. BY: Marcus

REF:

CC4/A15 23001448/UP3

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Sales@Leebrothers.com.sg

*Not Authorised*  
*10/2/23*  
*2/5 \$5400/*  
*4 days.*

Vehicle Number: SJE234Y

Vehicle Model: RANGE ROVER

PAGE 1

## PARTICULAR

## AMOUNT

QTY

SS

### NETTT PRICE

|   |                                               |                |                     |                |
|---|-----------------------------------------------|----------------|---------------------|----------------|
| 1 | FRONT BUMPER ASSY                             | <i>2e/torn</i> | \$ 3,327.22         |                |
| 1 | FRONT BUMPER LOWER GUARD -CTR                 | <i>torn</i>    | \$ 1,560.93         | <i>850</i>     |
| 2 | FRONT BUMPER PDC SENSOR @\$281.33             | <i>11</i>      | \$ 562.66           | <i>x</i>       |
| 2 | FRONT BUMPER SPRAY NOZZLE COVER -R/L @\$89.95 | <i>11</i>      | \$ 179.90           | <i>x</i>       |
| 1 | FRONT BUMPER TOP GUIDE -CTR                   | <i>one</i>     | \$ 441.59           |                |
| 2 | FRONT BUMPER SIDE GUIDE -R/L @\$110.25        | <i>11</i>      | \$ 220.50           | <i>x</i>       |
| 1 | FRONT BUMPER REINFORCEMENT                    | <i>11</i>      | \$ 1,855.90         | <i>x</i>       |
| 1 | FRONT GRILLE ASSY                             | <i>one</i>     | \$ 1,655.23         | <i>1005.22</i> |
| 1 | AIR INTERCOOLER                               | <i>11</i>      | \$ 1,860.59         | <i>x</i>       |
| 1 | AIR INTERCOOLER INTAKE DUCT                   | <i>torn</i>    | \$ 221.43           |                |
|   |                                               |                | \$ 11,885.95        |                |
|   |                                               |                | LESS 5%             | \$ 594.30      |
|   |                                               |                | <u>\$ 11,291.65</u> |                |

### SPECIAL NETT ITEMS

|   |                                      |            |                    |            |
|---|--------------------------------------|------------|--------------------|------------|
| 1 | (SET) FRONT BUMPER CLIP              | <i>11</i>  | \$ 50.00           | <i>✓</i>   |
| 1 | (SET) FRONT NUMBER PLATE WITH HOLDER | <i>but</i> | \$ 65.00           | <i>40</i>  |
| 1 | (SET) FRONT BUMPER WRAP STICKER      | <i>11</i>  | \$ 1,000.00        | <i>500</i> |
|   |                                      |            | <u>\$ 1,115.00</u> |            |

### LABOUR CHARGES

|                                                          |             |                    |
|----------------------------------------------------------|-------------|--------------------|
| TO CHECK FRONT ELECTRICAL WIRING                         | \$ 11 50.00 | <i>x</i>           |
| TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS            | \$ 600.00   | <i>350</i>         |
| TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS | \$ 600.00   | <i>300</i>         |
|                                                          |             | <u>\$ 1,250.00</u> |

## ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 13,656.65

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*5845.46*  
*52*  
*5513.18*  
*590*  
*650*  
*6793*