

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/AG/23001449/UVY3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: GBC 639X
 at Workshop m/s zero group
 of _____
 Insured: SKX68376
 Policy No. _____
 Claims No. C10020421/JL
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$88k.
 IDAC Accident Rport: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 2 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS B 8231
 Date: _____ Person Contacted: LIA 26549
 Vehicle: IN / OUT

Veh No: GBC 639X Yr Regn: 08/03/21
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Toyota hiace DX2.8 c.c. 2754
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 75380 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GDM/2012016592
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: in order / Jammed / Leaked / Burnt or
 Brake: in order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 Rear 6
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 09/02/23 D.O.I. 10/12/23
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 20/11k.
21/1/23 L/S & 5200 indom starley (red 5889.14, 53%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 6
 Resurvey No. of Trip: 2

Date/Time, File Return to?
 2) 21/2/23-typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
) \$ + RS, SI
) Photos
) Others
 TOTAL _____

Report Format : TP
 Lump Sum / t.B.t: (\$ 5200)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	823D
Vehicle Details	
Vehicle No.:	GBL639X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	1GD8668701
Chassis No.:	GDH2012016592
Maximum Power Output:	-
Open Market Value:	\$35,532.00
Original Registration Date:	08 Mar 2021
First Registration Date:	08 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$1,777.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Mar 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,889.00
COE Rebate Amount:	\$26,549.00
Total Rebate Amount:	\$26,549.00

The information contained herein is correct as at 10 Feb 2023

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. 90% Loan by
GV Cars Financing at 3.28% p.a.
Low Interest Rate
GV Automobile Centre StarAd

- Free VICOM evaluation
- Free grooming and 8 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

« Back (1 2) Next »

Sort by 20 results/page

38 vehicles





Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection

HIACE		Any	Any	2021	Any	Any	Any	Available
-------	--	-----	-----	------	-----	-----	-----	-----------



Toyota Hiace 2.8A DX

Fuel Type: Diesel

1 owner only! Pristine condition! Well taken care by previous owner! High loan available! High trade in! Hassle free hurry call fast to boo...

SG Motor Link Pte Ltd

Posted: 09-Feb-2023

\$91,800

\$11,290 /yr

30-Mar-2021

2,754 cc

-

Van

Available

PREMIUM AD



Toyota Hiace 3.0M

Fuel Type: Diesel

Best deals with us. Low mileage and smooth transmission. Fully serviced before handover, free front dash camera, full loan with \$0 dow...

Skylink Auto Pte Ltd

Posted: 09-Feb-2023

\$86,800

\$10,900 /yr

27-Jan-2021

2,982 cc

-

Van

Available

PREMIUM AD



Toyota Hiace 3.0M

Fuel Type: Diesel

First owner with low mileage well maintained regularly serviced.

Posted: 09-Feb-2023

\$85,000

\$10,700 /yr

19-Jan-2021

2,982 cc

-

Van

Available

DIRECT OWNER



Toyota Hiace 2.8A DX

Fuel Type: Diesel

Best deals with us. Low mileage and smooth transmission. Fully serviced before handover, free front dash camera, full loan with \$0 dow...

Skylink Auto Pte Ltd

Posted: 08-Feb-2023

\$92,800

\$11,400 /yr

31-Mar-2021

2,754 cc

-

Van

Available

PREMIUM AD



Draws Cool Air from Front to Rear for Van

Draws cool air from the front to the rear. Fits MPVs and Vans without aircon at the back. Compact size.

More info about this product



Toyota Hiace 2.8A DX

Fuel Type: Diesel

No.1 Highest Demand! Excellent For All Business Usage! Previous Owner letting go vehicle due to retirement. Servicing done. Condition l...

ABS Bus Pte Ltd

Posted: 08-Feb-2023

\$89,800

\$11,110 /yr

10-Mar-2021

2,754 cc

-

Van

Available

PREMIUM AD



Compare

Toyota Hiace Commuter 3.0A

Fuel Type: Diesel

Borneo unit just arrived. 11 passengers capacity with own install rear aircon done. New paintwork provided. Engine gearbox under carria...

I-Deal Auto Trading Pte Ltd

Posted: 08-Feb-2023

\$122,888

\$15,530 /yr

08-Jan-2021

2,982 cc

75,000 km

Bus

Available



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 5288887X

not authorized
 Hui moras
 10/1/23
 2/54 5200

QUOTATION

No : QT-000349

6 days
 take the the 1st

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

BLK 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924
 ATTN: MOTOR CLAIM DEPARTMENT
 TEL : 62212199/65402199 FAX : 67250853

Your Ref. : SKX6837G
 Vehicle No. : GBL639X
 Make & Model : TOYOTA HIACE
 Chasis No. : GDH2012016592
 Engine No. : 1GD8668701
 Accident Date : 09/02/2023
 Policy No. : 5121136922-01
 Date : 09/02/2023
 Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	LAMP (L/H/R) <i>cm</i>	1	PCS 328.90	328.90
2	CORNER PANEL (L/H/R) <i>cm</i>	1	PCS 134.20	134.20
3	REAR END PANEL (INNER) <i>Body 20/serf</i>	1	PCS 1,147.60	1,147.60
4	REAR END PANEL (OUTER) <i>Body 20</i>	1	PCS 297.80	297.80
5	FLOOR PANEL (REAR) <i>2</i>	1	PCS 710.50	710.50
6	REAR FLOOR TRIM <i>11</i>	1	PCS 110.30	110.30
7	BUMPER SIDE RETAINER (L/H/R) <i>cm</i>	1	PCS 24.50	24.50
8	BUMPER SIDE RETAINER (R/H/R) <i>cm</i>	1	PCS 24.50	24.50
9	FENDER SIDE RETAINER <i>cm</i>	2	PCS 26.80	53.60
10	REAR BUMPER	1	PCS 431.20	431.20
11	BUMPER CLIP	6	PCS 11.90 <i>1 set</i>	71.40
12	BUMPER BRACKET	4	PCS 42.50	170.00
13	REAR BOOT	1	PCS 1,755.30	1,755.30
14	REAR BOOT GARNISH	1	PCS 131.20	131.20
15	REAR BOOT OUTER HANDLE	1	PCS 105.90	105.90
16	REAR BOOT INNER LOCK	1	PCS 288.60	288.60
17	LOCK GARNISH	1	PCS 64.70	64.70
18	REAR BOOT LOCK STRIKER	1	PCS 102.30	102.30
19	CENTER LOCKING MOTOR (BOOT)	1	PCS 408.10	408.10
20	REAR BOOT WEATHERSTRIP	1	PCS 426.30	426.30
21	REAR BOOT INNER TRIM BOARD	1	PCS 583.40	583.40
22	REAR BOOT INNER TRIM BOARD CLIPS	16	PCS 3.90	62.40
23	DOOR ANTI SPLASH PLASTIC SEAL (BOOT)	1	PCS 56.10	56.10
24	LOGO	1	PCS 78.80	78.80
25	STICKER "1200KG"	1	PCS 34.30	34.30
26	STICKER "HIACE"	1	PCS 26.30	26.30
27	SPARE TYRE BRACKET	1	PCS 310.40	310.40

Rear step panel, serf \$ 326.50



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 5288887X

QUOTATION

No : QT-000349

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

BLK 190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
ATTN: MOTOR CLAIM DEPARTMENT

TEL : 62212199/65402199 FAX : 67250853

Your Ref. : SKX6837G
Vehicle No. : GBL639X
Make & Model : TOYOTA HIACE
Chassis No. : GDH2012016592
Engine No. : 1GD8668701
Accident Date : 09/02/2023
Policy No. : 5121136922-01
Date : 09/02/2023
Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
28	LOCK REGULATOR (SPARE TYRE) <i>11</i>	1	PCS 288.50 X	288.50
29	REAR BOOT CATCH <i>11</i>	2	PCS 44.00 X	88.00
30	REAR BOOT STOPPER BUSH (SIDE) <i>11</i>	2	PCS 25.30 X	50.60
31	Discount 25 %			-2,091.43
32	SubTotal (L)			6,274.27
33	REAR FLOOR BOARD <i>11</i>	1	PCS 450.00 X <i>S. Not item</i>	450.00
34	STICKER "70 Km/h" <i>11</i>	1	PCS 10.00 ✓	10.00
35	STICKER "8 PAX" <i>11</i>	1	PCS 10.00 ✓	10.00
36	REVERSE SENSOR <i>Shut</i>	1	SET 280.00 <i>200</i>	280.00
37	REVERSE CAMERA <i>11</i>	1	PCS 380.00 X	380.00
38	RIM <i>11</i>	1	PCS 180.00 X	180.00
39	TYRE (SPARE) <i>11</i>	1	PCS 220.00 X	220.00
40	REAR END PANEL SEALANT <i>11</i>	1	BTL 50.00 ✓	50.00
41	SEALANT (WINDSCREEN) <i>11</i>	1	PCS 35.00 ✓	35.00
42	REAR NUMBER PLATE <i>11</i>	1	PCS 35.00 X	35.00
43	SubTotal (S)			1,650.00
44	PANEL BEAT & REPAIR REAR DAMAGE	1	X 900	1,200.00
45	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1	X 700	900.00
46	TO PROVIDE UNDER TURFCODE	1	X 60	120.00
47	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1	X 20	80.00
48	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1	X	50.00
49	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	X 120	150.00
50	TO TRANSFER REAR BOOT FITTING	1	X 60	120.00
51	TO REMOVE REVERSE SENSOR/CAMERA	1	X 40	150.00
52	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1	X <i>Repaid</i>	150.00
53	SubTotal (LABOUR)			2,920.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000349

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

BLK 190 CLEMENCEAU AVENUE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

ATTN: MOTOR CLAIM DEPARTMENT

TEL : 62212199/65402199 FAX : 67250853

Your Ref. : SKX6837G
 Vehicle No. : GBL639X
 Make & Model : TOYOTA HIACE
 Chasis No. : GDH2012016592
 Engine No. : 1GD8668701
 Accident Date : 09/02/2023
 Policy No. : 5121136922-01
 Date : 09/02/2023
 Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
------	-------------	-----	-----------------	---------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-5791.40
 252
 P-4343.55
 S.N-305
 L-1900
 6548.55
 202
 5238

SINGAPORE DOLLAR TEN THOUSAND EIGHT HUNDRED FORTY FOUR AND CENTS TWENTY SEVEN ONLY

E. & O.E

Total	S\$	10,844.27
Discount	S\$	0.00
Net Total	S\$	10,844.27

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.