



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI23001449/Uvy3m4

Date: 22/02/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 6837G	Veh. Inspected	GBL 639X
Policy No.	P10114023R04	Coverage (\$)	0.00
Claim No.	C10020421/JL	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	09/02/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE DX 2.8 (A)	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GDH2012016592	Colour	SILVER
Odometer	75380 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	6 mm
L/H Front Tyre	195 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/02/2023	Inspection Date	10/02/2023
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**