

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsc303@singnet.com.sg

M/s : AIG Asia Pacific Insurance Pte. Ltd
78, Shenton Way,
#11-16, Singapore 079120

Attn : Motor Claims Department
Tel : 64193000
Fax : 62256772

Estimate bill : TT 08 / 23 / TP / WT

Registration No : FBS1904L

Make / model : Yamaha XSR155

Date : 10 / 02 / 2023

Mileage :
TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SJP1215M AND FBS1904L
ALONG DUNEARN ROAD ON 28 JANUARY 2023 AT ABOUT 1330HRS.

1pc Front steering handle
1set Front steering handle grip 120
1set Front steering handle balancer 75
1pc Front left wing mirror glass support
1pc Indicator signal switch
1pc Front left foot rest
1pc Front left foot rest bracket
1pc Selector gear lever
1pc Front main stand
1pc Front side stand
1pc Rear left foot rest
1pc Rear left foot rest bracket
1pc Rear swing arm 506
2pcs Rear swing arm bush
2pcs Rear swing arm bearing
2pcs Rear swing arm dust cover
1pc Rear glove box
Sub total :
Less 10% discount :
A total :

\$	RM	192.00	✓
\$	RM	150.00	✓
\$	RM	150.00	✓
\$	RM	42.00	✓
\$	RM	227.00	✓
\$	RM	42.00	✓
\$	RM	174.00	✓
\$	RM	133.00	✓
\$	RM	261.00	X
\$	RM	87.00	X
\$	RM	42.00	✓
\$	RM	167.00	✓
\$	RM	953.00	✓
\$	RM	176.00	✓
\$	RM	162.00	✓
\$	RM	56.00	X
\$	RM	545.00	✓
\$		3,559.00	
\$		355.90	
\$		3,203.10	

Remove and refit front steering handle, front steering handle grip, front steering handle balancer, front left wing mirror glass support, indicator signal switch, front left foot rest, front left foot rest bracket, selector gear lever, front main stand, front side stand, rear left foot rest, rear left foot rest bracket, rear swing arm, rear swing arm bush, rear swing arm bearing, rear swing arm dust cover, rear glove box.

\$ 600.00
\$ 3,803.10

Total amount for page 1:

Tropical Tech Automobile Services

(Authorised signature)

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte. Ltd**
78, Shenton Way,
#11-16, Singapore 079120

Attn : Motor Claims Department
Tel : 64193000
Fax : 62256772

Not Authorised

Estimate bill : TT 08 / 23 / TP / WT

Registration No : FBS1904L

Make / model : Yamaha XSR155

Mileage :

Date : 10 / 02 / 2023

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SJP1215M AND FBS1904L
ALONG DUNEARN ROAD ON 28 JANUARY 2023 AT ABOUT 1330HRS.

Remove and refit rear wheel.

Balancing rear wheel.

Wheel alignment test.

Balance brought forward from Page 1 :

Grand final amount :

\$	<i>na</i>	50.00	X
\$	<i>na</i>	50.00	X
\$		3,803.10	
\$		<u>3,903.10</u>	

Tropical Tech Automobile Services

(Authorised signature)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: