

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/HSB2300148/Upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLE7478R

Yr Regn:

29/07/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

)

Dep 12h.

NO 2016 model from SG car most

17/2/23 4/5 @ 4700 indur and see

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Tklee0247@gmail.com

Not Authorised
13/2/23
1/5 4700
4 days

Vehicle Number: SLE7478R

Vehicle Model: OPEL INSIGNIA

PARTICULAR		AMOUNT	
QTY	LIST PRICE	S\$	
1	1 REAR BUMPER	2542.65	\$ 2,886.50 ✓
2	1 REAR BUMPER TOW COVER-RH		\$ 48.50 X
3	2 REAR BUMPER PDC SENSOR@ 291.55	should	\$ 583.10 1pc
4	1 REAR BUMPER DIFUSSER	17	\$ 691.60 X
5	1 REAR BUMPER GUIDE-CTR	17	\$ 221.50 X
6	2 REAR BUMPER GUIDE - RH/LH @135	0/5cm	\$ 270.00 1pc
7	1 REAR BUMPER REINFORCEMENT	Buf 831	\$ 1,195.00 ✓
8	1 REAR BOOT LID	R	\$ 2,950.90 X
9	1 REAR BOOT CHROME MOULDING	17	\$ 831.50 X
10	1 REAR BOOT EMBLEM INSIGNIA	mm	\$ 121.50 ✓
11	1 REAR BOOT EMBLEM CDTI	mm	\$ 89.50 ✓
12	1 REAR BOOT LAMP - RH	17	\$ 510.60 X
13	1 REAR BOOT WEATHER STIP	17	\$ 231.50 X
14	1 REAR END PANEL	R	\$ 955.00 X
15	1 REAR TAILLAMP - RH	Cue 1099.20	\$ 1,590.00 ✓
16	1 REAR TAILLAMP PANEL - RH	R	\$ 235.00 X
			\$ 13,411.70
		LESS 10%	\$ 1,341.17
			\$ 12,070.53

SPECIAL NETT ITEMS

1	(SET) REAR BUMPER GUIDE REVERT PLUG	mm	\$ 120.00 60
1	(SET) BUMPER CLIP	mm	\$ 50.00 ✓
			\$ 170.00

LABOUR CHARGES

TO CHECK REAR WIRING	\$ 50.00 20
TO REMOVE AND REFIX REAR INTERIOR TIMRS	\$ 17 120.00 X
TO TUFF KOTE	\$ 17 60.00 X
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$ 1,080.00 700
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$ 900.00 450
	\$ 2,210.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 14,450.53

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5110.4
102
4899.36
110
1170