



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept			S1000010 / ICN13		M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433		
			Document No. 0				
			Document Date 09/02/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JHHAGV4620K003138		1GD9034948	60	Thomas Pang W T	---/---/----		0.00 ---/---/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCG22017213 ACC DATE:09.02.2023 TOW IN:09.02.2023 EXCESS: DATE-IN:09.02.2023 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				100.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				300.00	
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP				134.64	
4	B	BP-LAB2 R/I DASHBOARD ASSY TO FAC REPAIR.				1584.00	
5	B	BP-LAB2 R/I AC CON SYSTEM, BLOWER ASSY TO FAC REPAIR.				792.00	
6	B	BP-LAB2 R/I WIRE HARNESS ASSY TO FAC REPAIR.				792.00	
7	B	BP-WS2 R/I FRONT WINDSCREEN GLASS TO FAC REPAIR				594.00	
8	B	BP-LAB2 REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR				396.00	
9	B	BP-LAB2 TO REPLACE BRAKE SYSTEM, BOOSTER ASSY..				792.00	
10	B	BP-LAB2 TO REPLACE AIR BAG ASSY, CONTROL AND SEN SOR..				792.00	
11	B	BP-LAB2 TO REPLACE SAFETY BELT ASSY..				792.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICN13	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433
	Document No. 0	
	Document Date 09/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				134.64
13	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
14	B	BP-LAB2 REPLACE REAR EXHAUST PIPE				792.00
15	L	BP-LPO SUPPLY REGN PLATE (PO#)				160.00
16	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				7920.00
17	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				5248.00
18	S	BP-SUBLET SUPPLY COMPANY DOOR BLACK STICKER- 2PCS				100.00
19	1	T51211-25120 CROSSMEMBER, FRAME,	1.00	219.10		219.10
20	2	T51202-25170 CROSSMEMBER	1.00	0.00		
21	3	T51103-25020 REINFORCEMENT	1.00	0.00		
22	4	T51104-25010 REINFORCEMENT	1.00	0.00		
23	5	T52101-37985 BUMPER SUB-ASSY, FR	1.00	748.90		748.90
24	6	T52011-37140 ARM SUB-ASSY, FR	1.00	364.10		364.10
25	7	T52012-37140 ARM SUB-ASSY, FR	1.00	362.50		362.50
26	8	T81481-37040 COVER, FOG LAMP, RH	1.00	75.60		75.60
27	9	T81482-37040 COVER, FOG LAMP, LH	1.00	75.60		75.60
28	0	T53111-37A70 B1 GRILLE, RADIATOR	1.00	777.00		777.00
29	1	T67771-37040 RETAINER, DOOR TRIM	10.00	7.30		73.00
30	2	T53142-37010 GARNISH, RADIATOR	1.00	235.60		235.60
31	3	T53115-37100 BRACKET, RADIATOR	1.00	26.30		26.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept				S1000010 / ICN13		M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433			
				Document No. 0					
				Document Date 09/02/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JHHAGV4620K003138		1GD9034948	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
32	4	T53145-37040 CLIP, RADIATOR				2.00	4.40		8.80
33	5	T75392-37010 RETAINER, OUTSIDE				6.00	0.00		
34	6	T90159-60259 SCREW				2.00	3.00		6.00
35	7	T93560-14012 SCREW				2.00	2.60		5.20
36	8	T90467-10188 CLIP				6.00	3.40		20.40
37	9	T75315-37080 ORNAMENT, RADIATOR				1.00	84.60		84.60
38	0	T75311-37290 PLATE, FR NAME, NO.1				1.00	53.10		53.10
39	1	T53143-37010 GARNISH, RADIATOR				1.00	57.00		57.00
40	2	T56121-25040 WEATHERSTRIP,				1.00	443.40		443.40
41	3	T55078-37110 COVER SUB-ASSY, FR				1.00	374.20		374.20
42	4	T55738-37080 PROTECTOR, FR PANEL				1.00	109.50		109.50
43	5	T55700-37460 COWL ASSY				1.00	1434.30		1434.30
44	6	T53813-37170 B0 PANEL, FR SIDE, RH				1.00	392.50		392.50
45	7	T55785-37070 PAD, FR PANEL COVER				1.00	0.00		
46	8	T53814-37100 B1 PANEL, FR SIDE, LH				1.00	404.20		404.20
47	9	T55785-37070 PAD, FR PANEL COVER				1.00	0.00		
48	0	T90467-10162 CLIP				6.00	3.40		20.40
49	1	T55735-37021 REINFORCEMENT, COWL				1.00	47.90		47.90
50	2	T55736-37021 REINFORCEMENT, COWL				1.00	47.90		47.90
51	3	T53827-37010 PROTECTOR, FR FENDER				2.00	54.20		108.40
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts		Less Amount Due		
					Labour				
					Sublet				
					Lubrication/Fluid				
					Others				

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept			S1000010 / ICN13		M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433			
			Document No. 0					
			Document Date 09/02/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHHAGV4620K003138		1GD9034948	60	Thomas Pang W T	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
52	4	T67002-37323 PANEL SUB-ASSY, FR			1.00	2021.40		2021.40
53	5	T68610-37030 CHECK ASSY, FR DOOR			1.00	220.60		220.60
54	6	T68730-37010 HINGE ASSY, FR DOOR,			1.00	132.30		132.30
55	7	T68710-37020 HINGE ASSY, FR DOOR,			1.00	132.30		132.30
56	8	L90269-04051 RIVET			10.00	1.80		18.00
57	9	T90269-06013 RIVET			10.00	2.40		24.00
58	0	T81110-37660 HEADLAMP ASSY, RH			1.00	1412.70		1412.70
59	1	T81150-37660 HEADLAMP ASSY, LH			1.00	1412.70		1412.70
60	2	T86520-25150 HORN ASSY, LOW			1.00	162.10		162.10
61	3	T87010-25070 UNIT ASSY, AIR			1.00	0.00		
62	4	T87210-37100 CASE ASSY, AIR			1.00	405.80		405.80
63	5	T44610-25350 BOOSTER ASSY, BRAKE			1.00	1892.30		1892.30
64	6	T44704-25160 RESERVOIR SUB-ASSY,			1.00	280.70		280.70
65	7	T52105-25040 BUMPER SUB-ASSY, RR			1.00	997.80		997.80
66	8	T52151-25050 STAY, RR BUMPER, RH			1.00	314.60		314.60
67	9	T52152-25020 STAY, RR BUMPER, LH			1.00	314.60		314.60
68	0	T91552-11430 BOLT, FLANGE			3.00	0.00		
69	1	T90179-14007 NUT			3.00	5.90		17.70
70	2	T91552-01225 BOLT, FLANGE			3.00	4.60		13.80
71	3	T51961-36040 HOOK			1.00	128.90		128.90
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICNI3	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433
	Document No. 0	
	Document Date 09/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
72	4	T81550-25110 LAMP ASSY, RR	1.00	278.70		278.70
73	5	T81560-25100 LAMP ASSY, RR	1.00	278.70		278.70
74	6	T75135-25091 BRACKET, COMBINATION	1.00	71.30		71.30
75	7	T75136-25041 BRACKET, COMBINATION	1.00	69.90		69.90
76	8	T17430-11A51 PIPE ASSY, EXHAUST	1.00	839.70		839.70
77	9	T17420-11800 PIPE ASSY, EXHAUST,	1.00	673.90		673.90
78	0	T17565-31040 SUPPORT, EXHAUST	1.00	49.40		49.40
79	1	T85211-37251 ARM, FR WIPER, RH	1.00	167.70		167.70
80	2	T85221-37251 ARM, FR WIPER, LH	1.00	192.50		192.50
81	3	T85154-37030 PACKING, FR WIPER	2.00	30.10		60.20
82	4	T85070-25120 MOTOR & BRACKET	1.00	1065.20		1065.20
83	5	T85292-13010 CAP, WIPER ARM HEAD	2.00	14.50		29.00
84	6	T87905-37123 ARM SUB-ASSY, OUTER	1.00	720.70		720.70
85	7	T51701-37360 BRACKET SUB-ASSY,	1.00	0.00		
86	8	T51702-37100 BRACKET SUB-ASSY,	1.00	845.40		845.40
87	9	T52211-37010 SPACER, CAB FR	2.00	70.10		140.20
88	0	T54915-37230 SPRING, TILT CAB,	1.00	449.10		449.10
89	1	T54801-25130 TUBE SUB-ASSY, TILT	1.00	845.40		845.40
90	2	T90109-14013 BOLT	2.00	19.00		38.00
91	3	T90101-14079 BOLT, HEXAGON	4.00	16.70		66.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept			S1000010 / ICNI3		M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433		
			Document No. 0				
			Document Date 09/02/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JHHAGV4620K003138		1GD9034948	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
92	4	T54911-37160 ARM, TILT CAB SPRING	1.00	238.70		238.70	
93	5	T88718-25510 CLAMP, PIPING	1.00	0.00			
94	6	T55448-37040 C0 COVER, OIL RESERVOIR TANK, RH	1.00	32.70		32.70	
95	7	T87114-37010 COVER, HEATER	1.00	178.90		178.90	
96	8	T55301-37090 C0 PANEL SUB-ASSY,	1.00	1210.70		1210.70	
97	9	T73970-37040 C0 AIR BAG ASSY, INSTR	1.00	5043.20		5043.20	
98	0	T45130-37170 C0 PAD ASSY, STEERING	1.00	3269.80		3269.80	
99	1	T73210-37550 B0 BELT ASSY, FR SEAT,	1.00	1194.70		1194.70	
100	2	T73210-37550 B0 BELT ASSY, FR SEAT,	1.00	1194.70		1194.70	
101	3	T89970-37020 SENSOR ASSY, AIR	1.00	260.70		260.70	
102	4	T89170-25040 COMPUTER ASSY, AIR	1.00	2369.10		2369.10	
103	5	T84307-37020 CABLE SUB-ASSY,	1.00	1282.90		1282.90	
104	6	T55330-37210 REINFORCEMENT ASSY,	1.00	753.00		753.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 62,009.98
Please acknowledge receipt of vehicle			Parts 40,388.70		GST 8.00% 4,960.80		
			Labour 21,361.28				
			Sublet 260.00				
			Lubrication/Fluid 0.00		Less 0.00		
			Others 0.00		Amount Due 66,970.78		

Customer Copy