

ASS. REC. BY: Paul

REF:

CS/EG123 001469/Rny3

367R

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: 4Q 90724at Workshop m/s BORNEO MOTORof 2, PAMMAN CRESCENTInsured: EG1

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 114K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 4Q90724 Yr Regn: 2022/DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA DYNA 150 SMT C.C. 2755Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 4003 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2HHA4V4620K003138Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/75R15R: 145/80R13BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mm R/Bal. 5/5 mmL/Bal. 7 mm L/Bal. 5/5 mmD.O.A. 09/02/23 D.O.I. 13/02/23Survey held at BORNEODes. of Damages: FR / REAR / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR UNIT - 66K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Report Format: _____

Luman Sura / 11/12/16

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)

S + RS. SI

Photos

Others



code
 Reg No. : 196700086Z
 SST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept			S1000010 / ICN13		M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433			
			Document No. 0					
			Document Date 09/02/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHHAGV4620K003138		1GD9034948	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCG22017213 ACC DATE:09.02.2023 TOW IN:09.02.2023 EXCESS: DATE-IN:09.02.2023 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)						20 300.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP						134.64
4	B	BP-LAB2 R/I DASHBOARD ASSY TO FAC REPAIR.						1584.00
5	B	BP-LAB2 R/I AC CON SYSTEM, BLOWER ASSY TO FAC REPAIR.						792.00
6	B	BP-LAB2 R/I WIRE HARNESS ASSY TO FAC REPAIR.						792.00
7	B	BP-WS2 R/I FRONT WINDSCREEN GLASS TO FAC REPAIR						594.00
8	B	BP-LAB2 REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR						396.00
9	B	BP-LAB2 TO REPLACE BRAKE SYSTEM, BOOSTER ASSY..						792.00
10	B	BP-LAB2 TO REPLACE AIR BAG ASSY, CONTROL AND SEN SOR..						792.00
11	B	BP-LAB2 TO REPLACE SAFETY BELT ASSY..						792.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts	Less
			Labour	
			Sublet	Amount Due
			Lubrication/Fluid	
			Others	

Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details			
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433			
		Document No. 0				
		Document Date 09/02/2023				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				X 134.64
13	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
14	B	BP-LAB2 REPLACE REAR EXHAUST PIPE				396 192.00
15	L	BP-LPO SUPPLY REGN PLATE (PO#)				160.00
16	B	BP-LAB2 REPLACE ACC DAMAGED PARTS @ 792 X 7				5544 7920.00
17	B	BP-RES2 RESPRAY ACC AFFECTED AREAS @ 656 X 6				3936 5248.00
18	S	BP-SUBLET SUPPLY COMPANY DOOR BLACK STICKER- 2PCS				100.00
19	1	T51211-25120 CROSSMEMBER, FRAME, Lt	1.00	219.10		219.10
20	2	T51202-25170 CROSSMEMBER Lt	1.00	0.00		
21	3	T51103-25020 REINFORCEMENT ?	1.00	0.00		
22	4	T51104-25010 REINFORCEMENT ?	1.00	0.00		
23	5	T52101-37985 BUMPER SUB-ASSY, FR Torn	1.00	748.90		748.90
24	6	T52011-37140 ARM SUB-ASSY, FR Lt	1.00	364.10		364.10
25	7	T52012-37140 ARM SUB-ASSY, FR Lt	1.00	362.50		362.50
26	8	T81481-37040 COVER, FOG LAMP, RH ?	1.00	75.60		75.60
27	9	T81482-37040 COVER, FOG LAMP, LH ?	1.00	75.60		75.60
28	0	T53111-37A70 B1 GRILLE, RADIATOR mis	1.00	777.00		777.00
29	1	T67771-37040 RETAINER, DOOR TRIM mis	10.00	7.30		73.00
30	2	T53142-37010 GARNISH, RADIATOR mis	1.00	235.60		235.60
31	3	T53115-37100 BRACKET, RADIATOR Lt	1.00	26.30		26.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Borneo Motors



Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICN13 Document No. 0 Document Date 09/02/2023	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	4	T53145-37040 CLIP, RADIATOR <i>m</i>	2.00	4.40		8.80
33	5	T75392-37010 RETAINER, OUTSIDE <i>m</i>	6.00	0.00		
34	6	T90159-60259 SCREW <i>X</i>	2.00	3.00		6.00
35	7	T93560-14012 SCREW <i>X</i>	2.00	2.60		5.20
36	8	T90467-10188 CLIP <i>m</i>	6.00	3.40		20.40
37	9	T75315-37080 ORNAMENT, RADIATOR <i>rec</i>	1.00	84.60		84.60
38	0	T75311-37290 PLATE, FR NAME, NO.1 <i>m</i>	1.00	53.10		53.10
39	1	T53143-37010 GARNISH, RADIATOR <i>m</i>	1.00	57.00		57.00
40	2	T56121-25040 WEATHERSTRIP, <i>m</i>	1.00	443.40		443.40
41	3	T55078-37110 COVER SUB-ASSY, FR <i>bt</i>	1.00	374.20		374.20
42	4	T55738-37080 PROTECTOR, FR PANEL <i>m</i>	1.00	109.50		109.50
43	5	T55700-37460 COWL ASSY <i>bt</i>	1.00	1434.30		1434.30
44	6	T53813-37170 B0 PANEL, FR SIDE, RH ?	1.00	392.50		392.50
45	7	T55785-37070 PAD, FR PANEL COVER ?	1.00	0.00		
46	8	T53814-37100 B1 PANEL, FR SIDE, LH <i>m</i>	1.00	404.20		404.20
47	9	T55785-37070 PAD, FR PANEL COVER <i>m</i>	1.00	0.00		
48	0	T90467-10162 CLIP <i>m</i>	6.00	3.40		20.40
49	1	T55735-37021 REINFORCEMENT, COWL ?	1.00	47.90		47.90
50	2	T55736-37021 REINFORCEMENT, COWL ?	1.00	47.90		47.90
51	3	T53827-37010 PROTECTOR, FR FENDER <i>m</i>	2.00	54.20		108.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 #2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICN13	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433
	Document No. 0	
	Document Date 09/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	4	T67002-37323 PANEL SUB-ASSY, FR <i>bt</i>	1.00	2021.40		2021.40
53	5	T68610-37030 CHECK ASSY, FR DOOR <i>?</i>	1.00	220.60		220.60
54	6	T68730-37010 HINGE ASSY, FR DOOR, <i>?</i>	1.00	132.30		132.30
55	7	T68710-37020 HINGE ASSY, FR DOOR, <i>?</i>	1.00	132.30		132.30
56	8	L90269-04051 RIVET <i>wt</i>	10.00	1.80		18.00
57	9	T90269-06013 RIVET <i>wt</i>	10.00	2.40		24.00
58	0	T81110-37660 HEADLAMP ASSY, RH <i>cm</i>	1.00	1412.70		1412.70
59	1	T81150-37660 HEADLAMP ASSY, LH <i>cm</i>	1.00	1412.70		1412.70
60	2	T86520-25150 HORN ASSY, LOW <i>?</i>	1.00	162.10		162.10
61	3	T87010-25070 UNIT ASSY, AIR <i>?</i>	1.00	0.00		
62	4	T87210-37100 CASE ASSY, AIR <i>?</i>	1.00	405.80		405.80
63	5	T44610-25350 BOOSTER ASSY, BRAKE <i>?</i>	1.00	1892.30		1892.30
64	6	T44704-25160 RESERVOIR SUB-ASSY, <i>?</i>	1.00	280.70		280.70
65	7	T52105-25040 BUMPER SUB-ASSY, RR <i>bt</i>	1.00	997.80		997.80
66	8	T52151-25050 STAY, RR BUMPER, RH <i>bt</i>	1.00	314.60		314.60
67	9	T52152-25020 STAY, RR BUMPER, LH <i>bt</i>	1.00	314.60		314.60
68	0	T91552-11430 BOLT, FLANGE <i>?</i>	3.00	0.00		
69	1	T90179-14007 NUT <i>?</i>	3.00	5.90		17.70
70	2	T91552-01225 BOLT, FLANGE <i>?</i>	3.00	4.60		13.80
71	3	T51961-36040 HOOK <i>?</i>	1.00	128.90		128.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
go Insurance Pte Ltd Temasek Boulevard 4-01 Suntec Tower Five Singapore 038985 tn: Motor Claims Dept	S1000010 / ICN13	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433
	Document No. 0	
	Document Date 09/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
72	4	T81550-25110 LAMP ASSY, RR <i>ca</i>	1.00	278.70		278.70
73	5	T81560-25100 LAMP ASSY, RR <i>ca</i>	1.00	278.70		278.70
74	6	T75135-25091 BRACKET, COMBINATION <i>bt</i>	1.00	71.30		71.30
75	7	T75136-25041 BRACKET, COMBINATION <i>bt</i>	1.00	69.90		69.90
76	8	T17430-11A51 PIPE ASSY, EXHAUST <i>bt</i>	1.00	839.70		839.70
77	9	T17420-11800 PIPE ASSY, EXHAUST <i>?</i>	1.00	673.90		673.90
78	0	T17565-31040 SUPPORT, EXHAUST <i>?</i>	1.00	49.40		49.40
79	1	T85211-37251 ARM, FR WIPER, RH <i>out</i>	1.00	167.70		167.70
80	2	T85221-37251 ARM, FR WIPER, LH <i>?</i>	1.00	192.50		192.50
81	3	T85154-37030 PACKING, FR WIPER <i>x</i>	2.00	30.10		60.20
82	4	T85070-25120 MOTOR & BRACKET <i>?</i>	1.00	1065.20		1065.20
83	5	T85292-13010 CAP, WIPER ARM HEAD <i>x</i>	2.00	14.50		29.00
84	6	T87905-37123 ARM SUB-ASSY, OUTER <i>son</i>	1.00	720.70		720.70
85	7	T51701-37360 BRACKET SUB-ASSY, <i>bt</i>	1.00	0.00		
86	8	T51702-37100 BRACKET SUB-ASSY, <i>bt</i>	1.00	845.40		845.40
87	9	T52211-37010 SPACER, CAB FR <i>?</i>	2.00	70.10		140.20
88	0	T54915-37230 SPRING, TILT CAB, <i>?</i>	1.00	449.10		449.10
89	1	T54801-25130 TUBE SUB-ASSY, TILT <i>4</i>	1.00	845.40		845.40
90	2	T90109-14013 BOLT <i>?</i>	2.00	19.00		38.00
91	3	T90101-14079 BOLT, HEXAGON <i>?</i>	4.00	16.70		66.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	



Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
o Insurance Pte Ltd emasek Boulevard -01 Suntec Tower Five gapore 038985 : Motor Claims Dept	S1000010 / ICNI3	M/S Manikarnika Pte Ltd 77 High Street #01-09A High Street Plaza Singapore 179433
	Document No. 0	
	Document Date 09/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	GDY231R	TLMGV M1	20/12/2022	YQ9072Y	0	20120	72/UL/YQ9072Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
HHAGV4620K003138	1GD9034948	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
4	T54911-37160 ARM, TILT CAB SPRING ?	1.00	238.70		238.70
5	T88718-25510 CLAMP, PIPING ?	1.00	0.00		
6	T55448-37040 C0 COVER, OIL RESERVOIR TANK, RH ?	1.00	32.70		32.70
7	T87114-37010 COVER, HEATER ?	1.00	178.90		178.90
8	T55301-37090 C0 PANEL SUB-ASSY, <i>defect</i>	1.00	1210.70		1210.70
9	T73970-37040 C0 AIR BAG ASSY, INSTR <i>acc</i>	1.00	5043.20		5043.20
0	T45130-37170 C0 PAD ASSY, STEERING <i>acc</i>	1.00	3269.80		3269.80
1	T73210-37550 B0 BELT ASSY, FR SEAT, <i>acc</i>	1.00	1194.70		1194.70
2	T73210-37550 B0 BELT ASSY, FR SEAT, <i>acc</i>	1.00	1194.70		1194.70
3	T89970-37020 SENSOR ASSY, AIR <i>acc</i>	1.00	260.70		260.70
4	T89170-25040 COMPUTER ASSY, AIR <i>acc</i>	1.00	2369.10		2369.10
5	T84307-37020 CABLE SUB-ASSY, <i>acc</i>	1.00	1282.90		1282.90
6	T55330-37210 REINFORCEMENT ASSY, ?	1.00	753.00		753.00

*Paul
Hp 90010068
16 days
P/P
13/02/23 @ 1420
EXCESS: TBA
Reverse
Resy before print*

& on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	62,009.98
	Please acknowledge receipt of vehicle	Parts 40,388.70 Labour 21,361.28 Sublet 260.00 Lubrication/Fluid 0.00 Others 0.00	GST 8.00%	4,960.80
			Less	0.00
			Amount Due	66,970.78

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	367R
Vehicle No.:	YQ9072Y
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2022
Engine No.:	1GD9034948
Chassis No.:	JHHAGV4620K003138
Maximum Power Output:	7
Open Market Value:	\$31,608.00
Original Registration Date:	20 Dec 2022
First Registration Date:	20 Dec 2022
Transfer Count:	0
Actual ARF Paid:	\$1,581.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	19 Dec 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$48,333.00
COE Rebate Amount:	\$47,592.00
Total Rebate Amount:	\$47,592.00

The information contained herein is correct as at 14 Feb 2023

OK

Toyota Dyna 150 2.8A

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price **\$114,888** **Lifespan** **29-Dec-2042**

Depreciation **\$11,630 /yr** **Reg Date** **30-Dec-2022**
View models with similar depre (9yrs 10mths 15days COE left)

Mileage **N.A.** **Manufactured** **2021**

Road Tax **N.A.** **Transmission** **Auto**

Dereg Value **\$32,248 as of today (change)** **Fuel Type** **Diesel**

COE **\$32,641** **OMV** **\$33,610**

Engine Cap **2,755 cc** **ARF** **\$1,681**

Curb Weight **1,760 kg** **No. of Owners** **2**

Type of Vehicle **Truck**