

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/02/2023

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SHD6489T
Case Reference Number	TAX/02/23/2020
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG KOON MENG
Type of Accident	Open Door Case
Accident Date and Time	9/2/2023 2:30 PM
Accident Reported Date and Time	9/2/2023 4:00 PM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117598
Special Instruction to ARC, if any	TP/ LEFT PORTION
Prepared Date and Time	10/2/2023 10:49 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$0.00
Total Spray Cost	\$1,494.00	\$0.00
Total Spare Part Cost	\$2,969.24	\$0.00
Total Other Cost	\$520.00	\$0.00
TOTAL COST	\$5,490.24	\$0.00
Lump Sum Total	\$5,500.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	10/02/2023 11:07 AM	
Signature	☒	☒
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

APPROVED BY: [Signature]
DATE: 10/02/2023

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/02/2023

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR LH PORTION	\$507.00 400	
total Labour	\$507.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY FRONT DOOR LH	\$378.00 200	
O RESPRAY REAR DOOR LH	\$378.00 200	
O RESPRAY DOOR HANDLE F&R	\$360.00 100	
O RESPRAY REAR FENDER LH	\$378.00 200	
total Spray Painting & Panel Beating	\$1,494.00 700	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 30	
O TRANSFER DOOR MECHANISM	\$240.00 80	
O WASH AND VACUUM	\$60.00 XNW	
O REPLACE SUNDRY PARTS	\$100.00 XNW	
total Other Costs	\$520.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace BUC	/
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Nec	/
		7575647040	MOULDING, FRONT DOOR WINDOW FRAME, REAR LH	1.00	\$61.20	25.00	\$45.90	Replace Scr	/
		6921047051A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$423.20	25.00	\$317.40	Replace Br	/
		6921747020	DOOR FRONT, COVER OUTER HANDLE, LH	1.00	\$19.40	25.00	\$14.55	Replace Br	/
		6920247040	DOOR FRAME INNER HANDLE FRONT, LH	1.00	\$209.20	25.00	\$156.90 X	Replace ? CFA XNW	
		6924247030	DOOR PAD REAR, FRT & RR DOOR OUTER HANDLE, LH	1.00	\$17.80	25.00	\$13.35 X	Replace ? X NW	
		6924147020	DOOR PAD FRONT, FRT & RR DOOR OUTER HANDLE, LH	1.00	\$17.80	25.00	\$13.35 X	Replace ? X NW	
		7572047040	MOULDING ASSY, FRONT DOOR BELT, LH	1.00	\$99.90	25.00	\$74.93	Replace part	/
		6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,401.70	25.00	\$1,051.28 X	Replace Scr R	
		6789647010	WEATHERSTRIP, REAR DOOR, NO.2, LH	1.00	\$39.10	25.00	\$29.33 X	Replace Scr R	
		692114-7021A1	DOOR OUTER HANDLE REAR, LH	1.00	\$105.50	25.00	\$79.13 X	Replace Scr R	/
		7574047040	MOULDING ASSY, REAR DOOR BELT, LH	1.00	\$123.00	25.00	\$92.25 X	Replace XNW	
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33 X	Replace Scr R	
total					\$4,928.70		\$3,711.55		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
-------------	---------	--------------	-----------	----------	---------------	--------------	------------------	-----------	----------------

LKK Auto Consultants hence notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____
Acknowledged by Repaire

4 days L/S
1 rfen
10/2/23 5pm
Total Parts = 2351.77
1 rfen @ LKK Auto

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/03/2023

User ID : PohSuan

		61602471 60	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	100.00	\$0.00	Replace	Repair
Total					\$4,928.70		\$1,647.76		

R

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		69040471 00	LOCK ASSY, FRONT DOOR LH	1.00	\$607.90	10.00	\$547.11	Replace	Replace
		69202470 40	DOOR FRAME INNER HANDLE FRONT , LH	1.00	\$209.20	25.00	\$156.90	Replace	Replace
Total					817.10		704.01		

✓ BR
✓ BR

2,351.77
-20%
1881.42
+ 400.00
+ 810.00
3,091.42

L/S \$3,100/-