

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
 IOB Building #04-05
 Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department \ INDIA

Estimate No: EST1509285

Date: 03 Feb 2023

Policy No: GA600942

Veh Reg No: SLA3851T

Make/Model: SUBARU SUBARU XV
 1.6I-S AWD CVT

Chassis No: JF1GP3KC5GG165493

Engine No: FB16Y122784

Reg. Date: 29/02/2016

Your Ref No: TP 0223-7246

Claim Type: Third Party

Accident Date: 02/02/2023

TP Veh Reg No: SLT 3944 J

Estimate Repair Cost to Vehicle No :SLA3851T

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	594.6000	1 PC	594.60	
2 REAR BUMPER SIDE HOLDER - LH/RH	18.7000	2 PC	37.40	
3 REAR BUMPER CLIPS	3.9000	10 PC	39.00	
4 REAR BUMPER REINFORCEMENT	279.2000	1 PC	279.20	
5 REAR BUMPER REFLECTORS - LH/RH	28.4000	2 PC	56.80	
6 REAR BUMPER TOWING COVER - LH	21.0000	1 PC	21.00	
7 REAR PANEL	328.0000	1 PC	328.00	
8 REAR PANEL TOP GARNISH	100.5000	1 PC	100.50	
9 REAR BOOT	958.4000	1 PC	958.40	
10 REAR BOOT BOTTOM LOCK	200.3000	1 PC	200.30	
11 REAR BOOT SUBARU WORDINGS AND SYMMETRICAL AWD LOGO	70.8000	1 PC	70.80	
12 REAR BOOT XV WORDINGS	40.8000	1 PC	40.80	
13 REAR BOOT SUBARU LOGO	68.4000	1 PC	68.40	
14 REAR BOOT RUBBER	119.5000	1 PC	119.50	
15 REAR BOOT GLASS MOULDING TOP	39.4000	1 PC	39.40	
			2,954.10	
		Less 20%	590.82	2,363.28
Special Net				
16 REAR BUMPER SENSOR	220.0000	1 PCS	220.00	
17 REAR NUMBER PLATE WITH CASING	45.0000	1 PC	45.00	
			265.00	265.00
Labour				
18 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	700.0000	1 JOB	700.00	
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.0000	1 JOB	900.00	
20 TO CHECK WIRING	50.0000	1 JOB	50.00	
21 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.0000	1 JOB	100.00	
22 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	
23 TO REMOVE, REPLACE REAR EXHAUST PIPE	150.0000	1 JOB	150.00	
24 TO TUFF-KOTE	60.0000	1 JOB	60.00	
			2,040.00	2,040.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
IOB Building #04-05
Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department \ INDIA

Your Ref No: TP 0223-7246

Claim Type: Third Party

Accident Date: 02/02/2023

TP Veh Reg No: SLT 3944 J

Estimate No: EST1509285

Date: 03 Feb 2023

Policy No: GA600942

Veh Reg No: **SLA3851T**

Make/Model: SUBARU SUBARU XV
1.6I-S AWD CVT

Chassis No: JF1GP3KC5GG165493

Engine No: FB16Y122784

Reg. Date: 29/02/2016

Estimate Repair Cost to Vehicle No :SLA3851T

Description	U/Price	Quantity	Price	Amount
			SS	SS
			Total	S\$ 4,668.28
			Add GST @ 8%	373.46
			Total Amount Payable	S\$ 5,041.74

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FORTY ONE AND CENTS SEVENTY FOUR ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE