

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

14-Feb-23

Acknowledged by Repairer

Signature:

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6861 G

| | | | |
|-----------|---------------------------------------------------|-------------|--------|
| 1 pc | n/s rocker panel garnish <i>ser</i> | \$ 286.00 | ✓ |
| 1 pc | Rear n/s door <i>dent + R</i> | \$ 765.00 | R |
| 2 pcs | Rear n/s door hinges @ \$34.00 ? | \$ 68.00 | ? x NW |
| 1 pc | Rear n/s fender <i>dent + R</i> | \$ 1,205.00 | R |
| 1 pc | Rear n/s fender inner shield ? | \$ 120.00 | ? x NW |
| 1 pc | Rear bumper <i>cut + ser / cut</i> | \$ 696.00 | ✓ |
| 1 / 2 pcs | Rear bumper n/s & side bracket @ \$29.00 <i>X</i> | \$ 58.00 | ? x NW |
| | | \$ 3,198.00 | 982 |
| Less 10% | | \$ 319.80 | 98.20 |
| | | \$ 2,878.20 | 883.80 |

S/NETT

| | | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-------------|------|
| 1 set | Rear bumper clips <i>NEC</i> | \$ 48.00 | ✓ |
| 1 pc | Rear n/s fender sticker <i>NEC</i> | \$ 60.00 | ✓ |
| 1 set | Rear n/s fender inner shield clips <i>NEC</i> | \$ 38.00 | ✓ |
| 1 set | n/s door stickers <i>NEC</i> | \$ 100.00 | ✓ |
| Sundry | | \$ 50.00 | x NW |
| To check for rear n/s wheel alignment | | \$ 80.00 | 30 |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. | | \$ 180.00 | 60 |
| To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, n/s rocker panel garnish, rear bumper, etc | | \$ 1,200.00 | 600 |
| To putty and spray painting on rear bumper, n/s rear fender, n/s rocker panel garnish, rear n/s door | | \$ 800.00 | 700 |
| To apply rustproofing on the repaired and replaced panels. | | \$ 120.00 | 40 |
| | | \$ 5,554.20 | |

T = 2559.80
207 = 511.96

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST) *FT = 2047.84*
≈ 2050 *4 days.*

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

1 L/S 3 pm
14/2/23