

ASS. REC. BY:

REF:

AIS/ 230014941Kv

C

Kennerh

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. SP2002711186-01

Claims No. 202332005158

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$126K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 10-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: PNG 6440X

Yr Regn: 08.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Honda

Verel

c.c. 1496

Colour: M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading: 14865

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

RV3 1003188

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: _____

R: _____

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 6/2/23

D.O.A. 13/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/4 7803.80 Cash (red 8192.72, 51%)

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) 16/5/23-typist

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Transportation

S + RS. SI

Fees

Others

Report Format: Merimen


Lump Sum / I.B.I: (\$ 7803.80)

NOT Notarized
Ex @ 1100.
Penny B4point

5 days

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Date: 08/02/2023
Claim Type: OD
VRN: SNG6440X



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	BONNET	1	\$ 1,520.10	\$ 1,520.10
2	BONNET RUBBER - LH/RH	2	\$ 78.00	\$ 156.00
3	BONNET RUBBER - INNER	1	\$ 96.00	\$ 96.00
4	BONNET LOCK	1	\$ 237.00	\$ 237.00
5	BONNET INSULATOR	1	\$ 253.00	\$ 253.00
6	BONNET HINGE - LH/RH	2	\$ 98.00	\$ 196.00
7	SUPPORT PANEL TOP GARNISH	1	\$ 384.00	\$ 384.00
8	SUPPORT PANEL ASSY	1	\$ 868.00	\$ 868.00
9	FRONT BUMPER - TOP	1	\$ 1,350.70	\$ 1,350.70
10	FRONT BUMPER - LOWER	1	\$ 367.00	\$ 367.00
11	FRONT BUMPER SIDE RETAINER - LH/RH	2	\$ 31.80	\$ 63.60
12	FRONT BUMPER TOWING COVER - RH	1	\$ 68.00	\$ 68.00
13	FRONT BUMPER REINFORCEMENT	1	\$ 460.50	\$ 460.50
14	FRONT BUMPER FOGLAMP COVER - LH/RH	2	\$ 93.00	\$ 186.00
15	FRONT BUMPER FOGLAMP - LH/RH	2	\$ 395.00	\$ 790.00
16	FRONT BUMPER CENTRE LOWER GRILLE	1	\$ 256.00	\$ 256.00
17	FRONT BUMPER CENTRE LOWER LIP	1	\$ 395.00	\$ 395.00
18	FRONT FENDER O/S	1	\$ 785.40	\$ 785.40
19	FRONT FENDER OUTER ARCH GARNISH O/S	1	\$ 253.00	\$ 253.00
20	HEADLAMP ASSY O/S	1	\$ 2,150.80	\$ 2,150.80
21	HEADLAMP LOWER RETAINER O/S	1	\$ 102.00	\$ 102.00
22	FRONT GRILLE TOP BRACKET	1	\$ 39.00	\$ 39.00
23	FRONT GRILLE TOP GARNISH	1	\$ 87.00	\$ 87.00
24	FRONT GRILLE LOGO	1	\$ 98.00	\$ 98.00
25	FRONT GRILLE INNER	1	\$ 436.00	\$ 436.00
26	FRONT GRILLE OUTER	1	\$ 624.00	\$ 624.00
27	FRONT GRILLE TOP BRACKET - LH/RH	2	\$ 29.00	\$ 58.00
28	FRONT FENDER COWLING O/S	1	\$ 125.80	\$ 125.80
29	FRONT SHOCK ABSORBER O/S	1	\$ 310.70	\$ 310.70
30	FRONT LOWER ARM O/S	1	\$ 398.50	\$ 398.50
31	FRONT KNUCKLE O/S	1	\$ 335.10	\$ 335.10
32	FRONT KNUCKLE BEARING O/S	1	\$ 168.50	\$ 168.50
33	FRONT REINFORCEMENT	1	\$ 460.50	\$ 460.50
Subtotal				\$ 14,079.20
List discount				20.00%
Total				\$ 11,263.36

Repair Estimate

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	BONNET INSULATOR CLIP <i>nn</i>	8	\$ 3.50	\$	28.00 <i>X</i>
2	SUPPORT PANEL TOP GARNISH CLIP <i>nn</i>	8	\$ 3.50	\$	28.00 <i>X</i>
3	FRONT BUMPER CLIP <i>nn</i>	10	\$ 3.50	\$	35.00 <i>✓</i>
4	COOLANT <i>nn</i>	1	\$ 40.00	\$	40.00 <i>X</i>
5	FRONT NUMBER PLATE WITH FRAME <i>nn</i>	1	\$ 55.00	\$	55.00 <i>X</i>
6	GRILLE LOGO CLIP <i>nn</i>	2	\$ 2.50	\$	5.00 <i>X</i>
7	FRONT FENDER OUTER ARCH GARNISH O/S CLIPS <i>nn</i>	8	\$ 3.50	\$	28.00 <i>✓</i>
8	FRONT FENDER COWLING CLIPS <i>nn</i>	8	\$ 3.50	\$	28.00 <i>✓</i>
9	FRONT ALLOY WHEEL O/S <i>nn</i>	1	\$ 713.60	\$	713.60 <i>✓</i>
Total				\$	960.60

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00 <i>500l</i>
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00 <i>20l</i>
3	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00 <i>400l</i>
4	To rust proof all affected portions after repair.	0.5	\$ 100.00 <i>X</i>
5	To remove and replace o/s front rim. To perform tyre balancing.	0.25	\$ 50.00 <i>20l</i>
6	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00 <i>?</i>
7	To conduct computerized wheel alignment.	0.5	\$ 100.00 <i>60l</i>
Total labour			\$ 2,900.00

Estimate Grand Total	\$ 15,123.96
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

NOT Authorised
Ex @ 1100h
Penny Bepaint

5 days

\$ 7803.80

Make/Model: HONDA VEZEL 1.5A
Engine/Chassis No.: RV31003188
Date of accident:
Damaged area: O/S Front

Date: 08/02/2023
Claim Type: OD
VRN: SNG6440X



List items					
S/N	Parts description		QTY	UNIT PRICE	AMOUNT
1	BONNET	1	1	\$ 1,520.10	\$ 1,520.10
2	BONNET RUBBER - LH/RH	2	2	\$ 78.00	\$ 156.00
3	BONNET RUBBER - INNER	1	1	\$ 96.00	\$ 96.00
4	BONNET LOCK	1	1	\$ 237.00	\$ 237.00
5	BONNET INSULATOR	1	1	\$ 253.00	\$ 253.00
6	BONNET HINGE - LH/RH	2	2	\$ 98.00	\$ 196.00
7	SUPPORT PANEL TOP GARNISH	1	1	\$ 384.00	\$ 384.00
8	SUPPORT PANEL ASSY	1	1	\$ 868.00	\$ 868.00
9	FRONT BUMPER - TOP	1	1	\$ 1,350.70	\$ 1,350.70
10	FRONT BUMPER - LOWER	1	1	\$ 367.00	\$ 367.00
11	FRONT BUMPER SIDE RETAINER - LH/RH	2	2	\$ 31.80	\$ 63.60
12	FRONT BUMPER TOWING COVER - RH	1	1	\$ 68.00	\$ 68.00
13	FRONT BUMPER REINFORCEMENT	1	1	\$ 460.50	\$ 460.50
14	FRONT BUMPER FOGLAMP COVER - LH/RH	2	2	\$ 93.00	\$ 186.00
15	FRONT BUMPER FOGLAMP - LH/RH	2	2	\$ 395.00	\$ 790.00
16	FRONT BUMPER CENTRE LOWER GRILLE	1	1	\$ 256.00	\$ 256.00
17	FRONT BUMPER CENTRE LOWER LIP	1	1	\$ 395.00	\$ 395.00
18	FRONT FENDER O/S	1	1	\$ 785.40	\$ 785.40
19	FRONT FENDER OUTER ARCH GARNISH O/S	1	1	\$ 253.00	\$ 253.00
20	HEADLAMP ASSY O/S	1	1	\$ 2,150.80	\$ 2,150.80
21	HEADLAMP LOWER RETAINER O/S	1	1	\$ 102.00	\$ 102.00
22	FRONT GRILLE TOP BRACKET	1	1	\$ 39.00	\$ 39.00
23	FRONT GRILLE TOP GARNISH	1	1	\$ 87.00	\$ 87.00
24	FRONT GRILLE LOGO	1	1	\$ 98.00	\$ 98.00
25	FRONT GRILLE INNER	1	1	\$ 436.00	\$ 436.00
26	FRONT GRILLE OUTER	1	1	\$ 624.00	\$ 624.00
27	FRONT GRILLE TOP BRACKET - LH/RH	2	2	\$ 29.00	\$ 58.00
28	FRONT FENDER COWLING O/S	1	1	\$ 125.80	\$ 125.80
29	FRONT SHOCK ABSORBER O/S	1	1	\$ 310.70	\$ 310.70
30	FRONT LOWER ARM O/S	1	1	\$ 398.50	\$ 398.50
31	FRONT KNUCKLE O/S	1	1	\$ 335.10	\$ 335.10
32	FRONT KNUCKLE BEARING O/S	1	1	\$ 168.50	\$ 168.50
33	FRONT REINFORCEMENT	1	1	\$ 460.50	\$ 460.50
Subtotal					\$ 14,079.20
List discount					20.00%
Total					\$ 11,263.36

Special nett Items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	BONNET INSULATOR CLIP <i>NA</i>	8	\$ 3.50	\$ 28.00
2	SUPPORT PANEL TOP GARNISH CLIP <i>NA</i>	8	\$ 3.50	\$ 28.00
3	FRONT BUMPER CLIP <i>NA</i>	10	\$ 3.50	\$ 35.00
4	COOLANT <i>NA</i>	1	\$ 40.00	\$ 40.00
5	FRONT NUMBER PLATE WITH FRAME <i>NA</i>	1	\$ 55.00	\$ 55.00
6	GRILLE LOGO CLIP <i>NA</i>	2	\$ 2.50	\$ 5.00
7	FRONT FENDER OUTER ARCH GARNISH O/S CLIPS <i>NA</i>	8	\$ 3.50	\$ 28.00
8	FRONT FENDER COWLING CLIPS <i>NA</i>	8	\$ 3.50	\$ 28.00
9	FRONT ALLOY WHEEL O/S <i>NA</i>	1	\$ 713.60	\$ 713.60
Total				\$ 960.60

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
4	To rust proof all affected portions after repair.	0.5	\$ <i>NZ</i> 100.00
5	To remove and replace o/s front rim. To perform tyre balancing.	0.25	\$ 50.00
6	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00
7	To conduct computerized wheel alignment.	0.5	\$ 100.00
Total labour			\$ 2,900.00

Estimate Grand Total	\$ 15,123.96
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA VEZEL 1.5A

Engine/Chassis No.: RV31003188


Date of accident:

Damaged area: O/S Front

Date: 08/02/2023

Claim Type: OD

VRN: SNG6440X



Supplementary List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front fog lamp cover RH	Ref 1	\$ 85.00	\$ 85.00
2	Front fog lamp cover outer garnish RH	CM 1	\$ 45.50	\$ 45.50
3	Front fog lamp RH 510-70	CM 1	\$ 551.30	\$ 551.30
4	Front fog lamp inner bracket RH	CM 1	\$ 27.50	\$ 27.50
5	Front bumper sensor RH 126-70 shan	CM 1	\$ 303.10	\$ 303.10
6	Wiper washer tank	Ref 1	\$ 78.30	\$ 78.30
Subtotal				\$ 1,090.70
List discount				20.00%
Total				\$ 872.56

Supplementary Estimate Total	\$ 872.56
------------------------------	-----------