

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: WAN.VK.514306.N(W) Date: 12<sup>th</sup> May 2023

Our Ref: CS1/LAW23001498/Dny3m4

## M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBA 6091T INSURED VEHICLE: GBH 9834K

**ACCIDENT DATE: 13/06/2019** 

We thank you for your instruction on 30/01/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBA 6091T from M/s KTO Automobile Assessors.
- b) Singapore Accident Statement and Police Report of Vehicles FBA 6091T and GBH 9834K.
- c) Survey report by AJAX Inspection Services Pte Ltd with color photographs.
- d) Colour damaged vehicle photographs of FBA 6091T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBA 6091T Make & Model : Honda CB400

Year of Registration : 2006

Chassis Number : JH2NC39986M200102

Engine Capacity : 399 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.