



Occi_sono motor.com

Synergy@Kaki Bukit No.25 Kakit Bukit Road 4

#01-38 Singapore 417800

TEL / FAX: (65) 6744 0650

CASH SALES

NO: **2556**

Messrs FBA 6091T (Super 4 Honda CB400)
Mohammed Sanip Bin Jasmaui

Page 1 of 3

Date : 13 ^{Dec} ~~Jan~~ 2019

QUANTITY		DESCRIPTION	UNIT PRICE	AMOUNT
1	1	Handle bar	\$120	\$120
2	1 set	Handle bar balancer	\$20	\$20
3	1	Clutch lever	\$28	\$28
4	1 set	View mirror	\$120	\$120
5	1	Head lamp Assy	\$260	\$260
6	1	Meter Assy	\$925	\$925
7	1	Head lamp Rim	\$68	\$68
8	1	Head lamp Housing	\$75	\$75
9	1	Head lamp stay	\$85	\$85
10	1	Front Signal Lamp	\$65	\$65
11	1	Front Fender	\$216	\$216
12	2	Fork inner tube L/R	\$215	\$430
13	1	Fork under bracket	\$245	\$245
TOTAL AMOUNT				\$2657.00

Authorised Signature



Occi_sono motor.com

Synergy@Kaki Bukit No.25 Kaki Bukit Road 4

#01-38 Singapore 417800

TEL / FAX: (65) 6744 0650

CASH SALES

NO: **2557**

Messrs FBA 6091 T (Super 4 Honda CB400)

Mohammed Sanip Bin Jasmawi

Page 2 of 3

Date : 13 Dec ~~June~~ 2019

QUANTITY		DESCRIPTION	UNIT PRICE	AMOUNT	
1	1	Front Wheel Rim	\$ 750	\$ 750	
2	1	Front Brake Disc (Left Hand Side)	\$ 445	\$ 445	
3	1	Fuel Tank	\$ 890	\$ 890	
4	1	Engine Cover (Left Hand Side)	\$ 120	\$ 120	
5	1	Gear Shift Pedal	\$ 68	\$ 68	
6	1	Front footrest (Left Hand side)	\$ 55	\$ 55	
7	1	Footrest Bracket (Left Hand Side)	\$ 158	\$ 158	
8	1	Rear Footrest (Left Hand Side)	\$ 28	\$ 28	
9	1	Rear Cowling	\$ 285	\$ 285	
10	1	Rear Signal Lamp (left Hand Side)	\$ 65	\$ 65	
11	1	Engine Cover Gasket	\$ 8	\$ 8	
12	1	CDI (Capacitor Discharge Ignition)	\$ 700	\$ 700	
13	1	Key Set & reprogram	\$ 272	\$ 272	
TOTAL AMOUNT				\$ 3844/-	

Authorised Signature



Occi_sono motor.com

Synergy@Kaki Bukit No.25 Kaki Bukit Road 4

#01-38 Singapore 417800

TEL / FAX: (65) 6744 0650

CASH SALES

NO: 2558



Messrs FBA 6091T (Super 4 Honda CB400)

Mohamed Sanip Bin Jasmawati

Page 3 of 3

Date: 30 December 2019

Date : 22 October 2017

QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
1	1 set Fuel Tank Emblem	\$ 58	\$ 58
2	1 set Steering upper/lower Cone bearing	\$ 60	\$ 60
3	1 Front number Plate	\$ 10	\$ 10
4	2 Fork oil Seal & Dust Cover L/R	\$ 30	\$ 60
5	1 Fork oil	\$ 30	\$ 30
6	2 Towing (Transportation 2 Trips)	\$ 40	\$ 80
7	- Labour Charges (Replace, realign & Adjust above damage parts, Rim balancing check wiring, re-connection & lighting System)	\$ 450	\$ 450
8			
9			
10			
11			
12			
13			
TOTAL AMOUNT			\$ 748/-

Authorised Signature